

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION I 2100 RENAISSANCE BOULEVARD, SUITE 100 KING OF PRUSSIA, PENNSYLVANIA 19406-2713

December 10, 2012

Mr. Thomas J. Dougherty Vice President, Limerick Generating Station 3146 Sanatoga Road Pottstown, PA 19464

SUBJECT: LIMERICK GENERATING STATION REPLY TO NOTICE OF VIOLATION – NRC INTEGRATED INSPECTION REPORT 05000352/2012004 AND 05000353/2012004

Dear Mr. Dougherty:

Thank you for your letter of November 30, 2012 (ML12342A271) in response to our November 1, 2012, letter and Notice of Violation (ML12306A397) which cited Exelon for being in violation of Limerick Generating Station Unit 1 Technical Specification 6.8, "Procedures and Programs," when Limerick operators did not adequately implement an alarm response procedure when responding to a main control room alarm on July 11, 2012. Specifically, operators failed to immediately reduce power per the alarm response procedure after the main control room received the alarm condition. The NRC will review the implementation of your corrective actions during a future inspection to verify that full compliance has been achieved and maintained.

In accordance with Title 10 of the Code of Federal Regulations, Part 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspections in the NRC Public Document Room or from the Publicly Available Records (PARS) component of the NRC's document system (ADAMS). ADAMS is accessible from the NRC Web Site at http://www.nrc.gov/reading-rm/adams.html (the Public Electronic Reading Room).

Sincerely,

/RA/

Paul G. Krohn, Chief Projects Branch 4 Division of Reactor Projects

cc: Distribution via ListServ

Mr. Thomas J. Dougherty Vice President, Limerick Generating Station 3146 Sanatoga Road Pottstown, PA 19464

SUBJECT: LIMERICK GENERATING STATION REPLY TO NOTICE OF VIOLATION – NRC INTEGRATED INSPECTION REPORT 05000352/2012004 AND 05000353/2012004

Dear Mr. Dougherty:

Thank you for your letter of November 30, 2012 (ML12342A271) in response to our November 1, 2012, letter and Notice of Violation (ML12306A397) which cited Exelon for being in violation of Limerick Generating Station Unit 1 Technical Specification 6.8, "Procedures and Programs," when Limerick operators did not adequately implement an alarm response procedure when responding to a main control room alarm on July 11, 2012. Specifically, operators failed to immediately reduce power per the alarm response procedure after the main control room received the alarm condition. The NRC will review the implementation of your corrective actions during a future inspection to verify that full compliance has been achieved and maintained.

In accordance with Title 10 of the Code of Federal Regulations, Part 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspections in the NRC Public Document Room or from the Publicly Available Records (PARS) component of the NRC's document system (ADAMS). ADAMS is accessible from the NRC Web Site at http://www.nrc.gov/reading-rm/adams.html (the Public Electronic Reading Room).

Sincerely, /**RA**/ Paul G. Krohn, Chief Projects Branch 4 Division of Reactor Projects

cc: Distribution via ListServ

Distribution w/encl: (via E-mail)	
D. Roberts, DRP	D. Jackson, DRS
P. Wilson, DRP	E. DiPaolo, DRP, SRI
M. McLaughlin, ORA	P. Krohn, DRP
M. Gray, DRP	J. Hawkins, DRP, RI
A. Rosebrook, DRP	N. Esch, DRP, OA
S. Ibarrola, DRP	D. Holody, ORA

DOCUMENT NAME:	: G\DRP\BRANCH4\ENFORCEMENT\LGS\LIMERICK FAILURE TO FOLLOW ARC NOV ACKNOWLEDGMEN	Т
	LETTER - REV1 .DOCX	

ADAMS Accession	No: ML12345A177	200/				
SUNSI Review		$\mathbf{\nabla}$	Non-Sensitive	\checkmark	Publicly /	Available
			Sensitive		Non-Pub	licly Available
OFFICE	RI/DRP	RI/DRF	C			
NAME	ARosebrook/ AAR	PKrohr	n/ PGK			
DATE	12/07/12	12/10/	12			

OFFICIAL USE ONLY