NRC FORM 591M PART 1 (10-2011)* 10 CFR 2.201	2011)*				
	ETY INSPECTION REPORT	_			
LICENSEE/LOCATION INSPECTE Department of the Navy 2000 Navy Pentagon (2D25 Washington, DC 20350-200 Location: Puget Sound IMF San Diego, CA REPORT NUMBERS: 2012-013	3) 0	2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713			
3. DOCKET NUMBER	4. LICENSE NUMBER	5. DATES OF INSPECTION			
030-29462	45-23645-011	NA	December 13 & 14, 2012		
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X					
I hereby state that, within 30 days, the corrective actions is made in accordar	nce with the requirements of 10 CF	R 2.201 (corrective steps alrea	dy taken, corrective steps w	hich will be taken,	
date when full compliance will be achi Title	eved). I understand that no further Printed Name	written response to NRC will be	· · · · · · · · · · · · · · · · · · ·		
	Printed Name		Signature	Date	
LICENSEE'S REPRESENTATIVE					
NRC INSPECTOR	Shawn W. Seeley, Health F	Physicist	/RA/	12/27/12	
BRANCH CHIEF	Blake Welling, Chief		/RA/	1/2/13	
*NRC FORM 591M PART 1 (10-2011) 016.591M-Part1-non-Sensitive pu	ablic.docx	Docs\Current\Insp Record\I	R45-23645-01NA.2012-0		