NRC FORM 591M PART 1 U.S. NUCLEAR REGULATORY COMMISSION (10-2011)*				
10 CFR 2.201 SAF	ETY INSPECTION REPORT	AND COMPLIANCE IN	ISPECTION	
LICENSEE/LOCATION INSPECTED:		2. NRC/REGIONAL OFFICE		
Greenway Engineering, Inc. 151 Windy Hill Lane Winchester, VA 22602 REPORT NUMBER: 2013-001		U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713		
3. DOCKET NUMBER:	4. LICENSE NUMBER:		5. DATE OF INSPECTION	<u> </u>
		31470-01		
2. Previous violation(s) clos 3. The violation(s), specifical identified, non-repetitive exercise discretion, were exercise discretion. Non-cited violate 4. During this inspection, concited in accordance with	and regulations and the conditions of is, interviews with personnel, and obs findings, no violations were identified ed. ally described to you by the inspector, and corrective action was or is bein	f your license. The inspection servations by the inspector. I. Tas non-cited violations, are rig taken, and the remaining confollowing requirement(s) and the servations are right to the servation of the serva	n consisted of selective exar The inspection findings are a not being cited because they iteria in the NRC Enforcement corrective action(s):	minations of as follows: y were self- ent Policy, to
I hereby state that, within 30 days, the corrective actions is made in accordar date when full compliance will be achi	e actions described by me to the Insp nce with the requirements of 10 CFR	2.201 (corrective steps alrea	dy taken, corrective steps w	vhich will be taken,
Title	Printed Name		Signature	Date
LICENSEE'S REPRESENTATIVE				
NRC INSPECTOR	Scott Wilson		/RA/	1/9/13
BRANCH CHIEF	Blake Welling		/RA/	1/10/13
*NRC FORM 591M PART 1 (10-2011) (RI Rev. 06/04/2012) G:\DNMS\WordDocs\Current\Insp Record\R45-31470-01.2013001.591M-Part1.doc				
SUNSI Review Completed By:	/RA/ SWilson		X Public X	Non-Sensitive