



Acuren USA
BPX GPBU
Prudhoe Bay, Alaska
99734-0122
Phone: (907) 659-8249
Fax: (907) 670-7786
Materials Engineering and Testing
A Rockwood Company

February 9, 2013

G. Michael Vasquez, Chief
Nuclear Materials Safety Branch – A
Division of Nuclear Materials Safety

**SUBJECT: RESPONSE TO NRC INSPECTION REPORT 030-38596/2012-002 AND
NOTICE OF VIOLATION**

Mr. Vasquez:

A thorough review and discussion surrounding 10 CFR §20 Subpart M and the NRC Enforcement Policy section 6.9 was conducted by and with Acuren USA personnel responsible for providing reports to the NRC. This and discussions with NRC Inspector Mr. Jason Razo gives me confidence that this type of violation will be averted should the situation arise in the future. Additionally, if and when there is ever doubt as to the proper reporting requirements, or any other regulation interpretation questions, the responsible Acuren USA personnel are encouraged to contact the NRC for guidance.

Enhancements or modifications made to sections of our Operating and Emergency Procedures related to control drive mechanism maintenance is not addressed in this response per Mr. Razo's email dated February 7, 2013 since review of the new maintenance procedure has been accomplished.

Sincerely,

Robert L. Jefferson
Radiation Safety Officer, Alaska
Acuren USA Inc.
PO Box 340122
Prudhoe Bay, AK 99734
direct: 907-659-8249
mobile: 907-440-9012

Docket: 030-38596
License: 50-32443-01