NRC FORM 591M PART 1 U.S. NUCLEAR REGULATORY COMMISSION (10-2011) 10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION									
1. LICENSEE/LOCATION INSPECTED: 2. NRC/REGIONAL OFFICE									
Saint Mary's Health Care 200 Jefferson, S.E. Grand Rapids, MI 49503			Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352						
REPORT NUMBER(S) 13-01  3. DOCKET NUMBER(S)		4. LICENSE NUMBE	R(S)	5. DATE(S) OF INSPECTIO	N				
030-08291		21-01078-01		February 12, 2013					
LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:  Based on the inspection findings, no violations were identified.  2. Previous violation(s) closed.									
3. The violations(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.									
Statement of Corrective Actions  I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.									
TITLE	PRINTED NAME		SIGNATURE		DATE				
LICENSEE'S REPRESENTATIVE			,	,					
NRC INSPECTOR	Robert P. Hays	(	NA COM	Rus	elia la				
BRANCH CHIEF	Tamara E. Bloomer		It Sloome	0,	3/8/13				

NRC FORM 591M PART 3 (10-2011)	ח	ocket File Info		JCLEAR REGULATORY COMMISSION			
10 CFR 2.201 SAFE			COMPLIANCE IN	SPECTION			
1. LICENSEE/LOCATION INSPECTI	ED:		2. NRC/REGIONAL OFFICE				
Saint Mary's Health Care 200 Jefferson, S.E. Grand Rapids, MI 49503			Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352				
REPORT NUMBER(S) 13-01 3. DOCKET NUMBER(S)		4. LICENSE NUMBER(		5. DATE(S) OF INSPECTION			
030-08291		21-01078-01	5)	February 12, 2013			
6. INSPECTION PROCEDURES USE	D	7. INSPECTION FOCUS AREAS					
87131, 87132		03.01-03.07					
	SUPPLEME	NTAL INSPECT	ON INFORMATION				
1. PROGRAM CODE(S)	2. PRIORITY	3. LICENSEE CONTAC	Т	4. TELEPHONE NUMBER			
2240	2	Dale Schippers,	RSO	(616) 752-6744			
Main Office Inspection Next Inspection Date: 02/12/2015    Field Office Inspection  310 Lafayette Ave SE & 1000 E Paris Ave SE  Temporary Job Site Inspection							
license. The previous inspervious inspection, the I activities at 310 Lafayette inspection. East Paris A only. The licensee's Nucl one nuclear medicine tectstudies are routinely conclocal nuclear pharmacy. limited quantity shipment inspection.  Performance Observation  During the inspections, the surveys; (2) package recent HAZMAT training; (5) ure (7) sealed source inventors.	c nuclear medicine process a camera line sources pection reviewed lice icensee has added and e Ave. SE, not inspectivenue SE, Suite 200, lear Medicine Departs and Monday-Wedra Monday-Wedra All waste was either list. No licensed activities	The licensee has ensed activities at additional ALOU ted during the pretent the licensee is aument routinely control other NMTs rotated for decay-inties have been control of the licensee is aument routinely control other NMTs rotated for decay-inties have been control of the licensee is aument routinely control of the licensee is aument routinely control of the licensee is aument	se and high dose brachy is four authorized location 200 Jefferson Ave. and and was reviewed during vious inspection, were rethorized for 10 CFR 35 anducts an average of 4-5 te from the other St. Mays, each week. The licent storage (DIS) or returned at 310 Lafayette assed as applicable: (1) suggested as applicable: (1) suggested assay procedures; (6) age of licensed material				
The inspector performed independent and confirmatory radiation measurements, which indicated results consistent with licensee survey records and postings.							