NRC FORM 591M PART 1 (10-2011)* 10 CFR 2.201			J.S. NUCLEAR REGULATO	RY COMMISSION
	ETY INSPECTION REPORT	_		
1. LICENSEE/LOCATION INSPECTED: Pole Brothers Imaging Company, LLC 1217 Senseny Road Winchester, Virginia 22602 REPORT NUMBER 2013-002		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713		
3. DOCKET NUMBER	4. LICENSE NUMBER		5. DATE(S) OF INSPECTI	ION
030-34342	45-25383	3-01	-01 April 23-24, 2013	
2. Previous violation(s) close 3. The violation(s), specifical identified, non-repetitive, exercise discretion, were Non-cited violat 4. During this inspection, certiced in accordance with terms.	is, interviews with personnel, and ob findings, no violations were identified ed. Ally described to you by the inspector, and corrective action was or is being	or as non-cited violations, are not taken, and the remaining confoliowing requirement(s) and below and/or attached, were form is a NOTICE OF VIOLAT	The inspection findings are a not being cited because they riteria in the NRC Enforcement corrective action(s):	as follows: y were self- ent Policy, to nents and are being
I hereby state that, within 30 days, the corrective actions is made in accordar date when full compliance will be achieved.	e actions described by me to the Ins	R 2.201 (corrective steps alrea	ady taken, corrective steps w	vhich will be taken,
Title	Printed Name		Signature	Date
LICENSEE'S REPRESENTATIVE	Charles Tadpole Hilbert, RS	80		
NRC INSPECTOR	Craig Gordon, Sr. Health Pl	hysicist	/RA/	5/7/13
BRANCH CHIEF	Blake Welling, Chief MS&I I	Branch	/RA/	5/7/13
*NRC FORM 591M PART 1 (10-2011) SUNSI Review Completed By:) (RI Rev. 06/04/2012) G	:\WordDocs\Current\Insp Rec	ord\R45-25383-01.2013002.	.591M-Part1.docx Non-Sensitive