From: Hickman, John

Sent: Monday, June 10, 2013 4:48 PM

To: Donald A. Beckman

Subject: Another Heavy Loads Amendment Question

Attachments: Question on page 24 of 53.pdf

Don,

Please see the attached page markup. Dan needs you to explain:

- (1) the relationship in between shear wall column P7, P4, etc. to the SFP column 17 to 23 and P to W? (Yellow Highlight),
- (2) missing Value (Green Highlight), and
- (3) below Table, foot note *SSE Max. Moment (IR = 1.111). This interaction ratio (IR) is unacceptable (need to see a conservative reanalysis [method] that has an IR below unity.

Thanks, John