

**Open Generic Communication TACs (PA No. 115126CA/B)
Summary Report (AS OF 06/30/2013)**

TAC NO.	TAC TITLE	AGE (Mon)	TAC OPENED	LEAD ORG
ME5167	RIS 'Staff Position on the Clarification of Submitting of Alter. Under 10 CFR 50.55'	31.0	12/13/2010	DE
ME9020	RIS 'Embedded Digital Devices in Safety Systems'	12.0	07/09/2012	NRO
ME9732	RIS 'Resolution of Top Nozzles Stress Corrosion Cracking Issues'	9.0	10/04/2012	NMSS
MF0541	RIS 'NRC Position on SSCs Requiring Protection from Tornado Missiles	6.0	01/23/2013	DSS
MF1404	RIS 'Withdrawal of NRC Generic Letter 95-08 and Endorsement of NEI 11-08'	3.0	04/10/2013	NSIR
MF1505	RIS 'Removal of SGI Designation from Order EA-02-081 Issued January 7, 2003'	3.0	04/30/2013	NSIR
MF1739	RIS 'Developing Inservice Testing and Inservice Inspection Programs under 10 CFR Part 52 Rev 1'	2.0	05/02/2013	PLPB
MF1773	RIS 'License Renewal Guidance for Part 50 versus Part 54 Issues'	2.0	05/13/2013	DLR
MF2273	RIS 'Enhancements To The Vendor Inspection Program'	1.0	06/18/2013	NRO
MF2303	RIS 'Gas Management'	1.0	06/25/2013	PLPB
MF0580	IN 'Radioactive Effluent Radiation Monitoring Systems'	6.0	01/29/2013	DPR
MF0921	IN 'Quasi-Laminar Indications in Reactor Pressure Vessel Forgings'	4.0	03/08/2013	DE
MF0922	IN 'Welding Problems During Fabrication of Reactor Plant Components'	4.0	03/08/2013	NRO

**Open Generic Communication TACs (PA No. 115126CA/B)
Summary Report (AS OF 06/30/2013)**

TAC NO.	TAC TITLE	AGE (Mon)	TAC OPENED	LEAD ORG
MF1357	IN 'Refueling Water Storage Tanks'	3.0	04/03/2013	PGCB
MF1394	IN 'Freespan Cracks in 600 TT Tube Material'	3.0	04/09/2013	DE
MF1740	IN 'Potential Design Deficiency in Motor-Operated Valve Control Circuitry'	2.0	05/02/2013	DE
MF1775	IN 'Recent Instrument Sensing Line Sloping Problems Caused By Improper Design and/or Installation'	2.0	05/13/2013	NRO
MF1794	IN 'Flange Leakoff Line Inspection'	2.0	05/16/2013	DE
MF1836	IN 'Willful Misconduct/Record Falsification and Nuclear Safety Culture'	2.0	05/17/2013	NRO
MF1921	IN 'Teflon Material Degradation Affecting Containment Integrity and Class 1E EQ Functions'	2.0	05/31/2013	DORL
MF2269	IN 'Containment Liner Plate Leak Chase Channels Degradation'	1.0	06/17/2013	DE
MF2313	IN 'Steam Generator Channel Head and Tubesheet Degradation'	1.0	06/25/2013	DE
ME9142	GL 'Post-Fire Safe-Shutdown Circuit Analysis Spurious Actuations'	12.0	07/26/2012	DRA
ME9843	GL 'Treatment of Natural Phenomena Hazards At Fuel Cycle Facilities'	9.0	10/25/2012	NMSS
MF0581	GL 'Degradation of Neutron Absorbing Material in Spent Fuel Pools'	6.0	01/29/2013	DSS