



**UNITED STATES
NUCLEAR REGULATORY COMMISSION**
REGION II
245 PEACHTREE CENTER AVENUE NE, SUITE 1200
ATLANTA, GEORGIA 30303-1257

July 16, 2013

MEMORANDUM TO: Anthony T. Gody, Director
Division of Fuel Facility Inspection

FROM: James A. Hickey, Chief */RA/ J. Diaz for*
Fuel Facility Inspection Branch 2
Division of Fuel Facility Inspection

SUBJECT: SUMMARY OF NUCLEAR REGULATORY COMMISSION
PUBLIC OUTREACH MEETING ON JULY 09, 2013, IN
METROPOLIS, ILLINOIS (DOCKET 40-3392)

SUMMARY: This memorandum refers to the public outreach meeting conducted at
the Community Center in Metropolis, IL on July 9, 2013.

The NRC began the public meeting with an introduction by the Region II Division Director for Fuel Facility Inspection followed by presentations by panel members on the NRC's Technical Evaluation Report (TER), Emergency Planning, and NRC's Inspection Effort at Honeywell during the shutdown, and an overview of the Regional Oversight Panel discussed in further detail in the following paragraph.

Through the technical review conducted by NRC Headquarters staff documented in the TER along with on-site inspections by Regional Inspectors, the NRC has concluded that the modifications and their supporting analysis to the Honeywell Metropolis Works (MTW) facility provides for reasonable assurance of adequate protection for both the worker and public. The NRC staff inspected Honeywell's implementation of facility modifications and found that Honeywell adequately implemented procedures relating to quality procurement, commercial grade dedication, material control and storage, design change, and work implementation. The staff also verified that the as-built facility was appropriately represented in design documents. The NRC staff observed Honeywell's emergency exercise and subsequent re-demonstration of areas needing improvement and concluded that Honeywell was capable of implementing its revised Emergency Response Plan. The NRC staff also found that Honeywell implemented effective corrective actions to ensure the appropriate correction of any issues identified during the implementation of facility modifications. In addition, the staff inspected the MTW facility's operating procedures and operator training, concluding that the facility operators are ready to operate the facility in a safe manner.

Based on the results of the TER, emergency exercise, and on-site inspections, the NRC Oversight Panel comprised of Regional and Headquarters management, recommended to the Administrator of Region II to authorized resumption of licensed operations at the MTW Facility.

Following the presentations, the public meeting was opened for general questions and answers.

The meeting accomplished the goal of communicating information related to NRC activities as it pertained to the resumption of licensed activities at Honeywell in a public setting that offered the opportunity to ask questions directly to the subject matter experts.

Documents provided to the public or used during the meeting are available via the Agencywide Document Access and Management System (ADAMS) using the Accession Numbers listed in Enclosure 2.

Enclosures:

1. List of Meeting Attendees
2. List of Documents in ADAMS

Based on the results of the TER, emergency exercise, and on-site inspections, the NRC Oversight Panel comprised of Regional and Headquarters management, recommended to the Administrator of Region II to authorized resumption of licensed operations at the MTW Facility.

Following the presentations, the public meeting was opened for general questions and answers.

The meeting accomplished the goal of communicating information related to NRC activities as it pertained to the resumption of licensed activities at Honeywell in a public setting that offered the opportunity to ask questions directly to the subject matter experts.

Documents provided to the public or used during the meeting are available via the Agencywide Document Access and Management System (ADAMS) using the Accession Numbers listed in Enclosure 2.

Enclosures:

1. List of Meeting Attendees
2. List of Documents in ADAMS

Distribution w/encls:

Region II Public Affairs Officer

- J. Weil, OCA
- V. McCree, RII
- L. Wert, RII
- A. Gody, RII
- M. Lesser, RII
- J. Pelchat, RII
- G. Woodruff, RII
- M. Bailey, NMSS
- P. Silva, NMSS
- T. Liu, NMSS
- B. Reilly, NMSS
- J. Hickey, RII
- R. Gibson, RII
- PUBLIC

X PUBLICLY AVAILABLE NON-PUBLICLY AVAILABLE SENSITIVE X NON-SENSITIVE
 ADAMS: X Yes ACCESSION NUMBER ML13197A200 X SUNSI REVIEW COMPLETE

OFFICE	RII:DFFI						
SIGNATURE	/RA/						
NAME	RGibson						
DATE	7/ 16 /2013	7/ /2013	7/ /2013	7/ /2013	7/ /2013	7/ /2013	7/ /2013
E-MAIL COPY?	YES NO	YES NO	YES NO	YES NO	YES NO	YES NO	YES NO

OFFICIAL RECORD COPY DOCUMENT NAME: G:\DFFI\Branch 2\Honeywell\Honeywell Restart Authorization 2013\Public Meeting Documents\HW CAT III meeting summary July 2013.docx

LIST OF ATTENDEES

U. S. Nuclear Regulatory Commission

A. Gody	N. Peterka
J. Hickey	R. Hannah
M. Norris	K. Morrissey
D. Hartland	J. Marciano
M. Bailey	A. Chowdhury

State and Local Government

B. McDaniel	R. Pollard
H. Masse	P. Carter
K. Davis	J. Mansfield
J. Miller	D. Lanier

Honeywell Metropolis Works

L. Smith	C. Pachcco	U. Out
M. Wolf	D. Bilski	T. Noll
J. Cybuski	P. Nelson	J. Price
B. St. Peter	D. Garcia	H. Heater
L. Richardson	D. Craig	E. Rowley
T. Dodd	B. Perriello	R. Coa
D. Hage	N. Smith	M. Mena
E. Robinson	R. Rabertson	R. Apren
J. King	J. Cross	J. Pitchett

MEMBERS OF THE PUBLIC

E. Fields	M. Campell	M. Boren
J. Thomas	R. Allshouks	D. Miller
J. Rodabough	G. Vander Boegh	T. Thompson
S. Rodabough	B. Stokes	

1. Honeywell Emergency Planning – ML13192A316
2. Honeywell Regional Oversight Panel – ML13192A335
3. Technical Evaluation Report – ML13192A339
4. NRC Inspection Effort at the Honeywell Metropolis Works Facility – ML13197A157
5. NRC Oversight of Honeywell Metropolis Works – ML13192A342

Enclosure 2