NRC FORM 591M PART 1 (10-2011)* 10 CFR 2.201  SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION			
LICENSEE/LOCATION INSPECTED:  University of Puerto Rico Medical Sciences Campus P.O. Box 365067 San Juan, Puerto Rico 00936-5067 REPORT NUMBER(S)  2013-001		2. NRC/REGIONAL OFFICE  U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713	
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(	5. DATE(S) OF INSPE	ECTION
030-13584	52-01946-07	June 11-12, 2013	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:  X			
corrective actions is made in accordan	e actions described by me to the Insp nce with the requirements of 10 CFR	ector will be taken to correct the violations identified. 2.201 (corrective steps already taken, corrective steritten response to NRC will be required, unless spec	ps which will be taken,
Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Tara L. Weidner/Robert Gall	aghar /RA/	6/12/13
BRANCH CHIEF	James P. Dwyer	/RA PLanzisera f/	7/10/13
*NRC FORM 591M PART 1 (10-2011) (RI Rev. 06/04/2012) G:\WordDocs\Current\Insp Record\R52-01946-07.2013-001.591M-Part1.doc			
SUNSI Review Completed By:	/RA/ TLWeidner	x Public	x Non-Sensitive