

College of Engineering UF Training Reactor Facility

202 Nuclear Sciences Center PO Box 118300 Gainesville, FL 32611-8300 352-294-2104 bshea@ufl.edu

July 10, 2013

ATTN: Document Control Desk
U.S. Nuclear Regulatory Commission

10 CFR 50.54(p) UFTR Operating License R-56, Docket 50-83

Washington, D.C. 20555-0001

Subject: Security Plan Change Performed Under 10 CFR 50.54(p)

The UFTR has replaced a wooden door with a metal door. No loss of safeguards effectiveness results from the replacement.

This submittal has been reviewed and approved by UFTR management and by the Executive Committee of the Reactor Safety Review Subcommittee.

Please let us know if you need further information.

I declare under penalty of perjury that the foregoing is true and correct to my knowledge.

Executed on July 10, 2013.

Brian Shea Reactor Manager

BS/djc

cc: Dean – College of Engineering

Reactor Safety Review Subcommittee

UFTR Facility Director UFTR Reactor Manager UFTR Licensing Engineer NRC Project Manager