



John Muir Medical Center
Concord Campus

2540 East Street
Concord, CA 94520

T. (925) 682-8200

06/11/2013

Director, Office of Federal and State Materials
and Environmental Management Programs
ATTN: Document Control Desk/GLTS
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555-0001

In fulfillment of the requirements of 10 CFR 31.5 (c) 8, we hereby notify you that on 06/11/13 we transferred the self-luminous exit signs listed on the attached spreadsheet to SRB Technologies Inc. 2580 Landmark Dr, Winston-Salem, NC 27103 North Carolina License # 034-0534-2. As required, for each sign listed on the spreadsheet, we include the name of the manufacturer, model number, and serial number.

If you should have any questions, please contact Mike Rijavec (925) 674-2266.

Sincerely,

A handwritten signature in black ink, appearing to read "Mike Rijavec", with a long horizontal line extending to the right.

Mike Rijavec
Chief Engineer
Mike.Rijavec@johnmuirhealth.com

Encl.

20130611 10:00 AM [Faded text]

[Faded text]

FSMEID



This Serial Number Log must also accompany each box as a packing slip and so must accurately reflect the inventory of EACH box.

Inventory Box Number: 1 of 3

Line	Manufacturer Name	Model Number	Serial Number	Date of Manufacture	Activity (Ci or TBq amount)
1	ISOLITE	2000	A27411	7-92	9.5
2	ISOLITE	2000	A27413	7-92	9.5
3	ISOLITE	2000	A27419	7-92	9.5
4	ISOLITE	2000	A27407	7-92	9.5
5	ISOLITE	2000	A27414	7-92	9.5
6	ISOLITE	2000	A27415	7-92	9.5
7	SHIELD SOURCE	101	H5854	11-94	7.5
8	SHIELD SOURCE	101	H5853	11-94	7.5
9	SRB TECHNOLOGIES	N/A	169033	9-93	20
10	SRB TECHNOLOGIES	N/A	169032	9-93	20

L.M. RISAJEC
Name

925-674-2267
Phone #


Please email this log to sales@tritiumdisposal.com or fax to: 614-863-0622.
Make sure to include your contact info if you have not already been assigned a TritiumDisposal.com account rep.



This Serial Number Log must also accompany each box as a packing slip and so must accurately reflect the inventory of EACH box.

Inventory Box Number: 3 of 3

Manufacturer Name	Model Number	Serial Number	Date of Manufacture	Activity (Ci or TBq amount)
ISOLITE	2000	A27416	7-92	9.5
ISOLITE	2000	A27422	7-92	9.5
ISOLITE	2000	A27423	7-92	9.5
ISOLITE	2000	A27406	7-92	9.5
ISOLITE	2000	A27408	7-92	9.5
ISOLITE	2000	A27409	7-92	9.5
ISOLITE	2000	A27410	7-92	9.5
ISOLITE	2000	A27412	7-92	9.5
ISOLITE	2000	A27417	7-92	9.5
ISOLITE	2000	A27418	7-92	9.5


Initial

5-22-13
Date

Please email this log to sales@tritiumdisposal.com or fax to: 614-863-0622.
Make sure to include your contact info if you have not already been assigned a TritiumDisposal account rep.



This Serial Number Log must also accompany each box as a packing slip and so must accurately reflect the inventory of EACH box.

Inventory Box Number: 2 of 3

Line	Manufacturer Name	Model Number	Serial Number	Date of Manufacture	Activity (Ci or TBq amount)
1	SHIELD SOURCE	101	H5852	11-94	7.5
2	SAFETY SIGN	BETALUX E	168898	9-93	20
3	OMNI GLO	700	9304	6-93	20
4	SRB TECHNOLOGIES	BETALUX E	182629	9-95	20
5	SRB TECHNOLOGIES	BETALUX E	168899	9-93	20
6	SRB TECHNOLOGIES	BETALUX E	182631	9-95	20
7	OMNIGLO	MODEL 700 OMNIGLO	9305	5-98	20
8	SHIELD SOURCE	LTE	H0930	3-94	8.5
9	SHIELD SOURCE	101	H5855	11-94	7.5
10	ISOLITE	2000	A27421	7-92	9.5

L. M. RISAUEC
Name

925-674-2267
Phone #

Please email this log to sales@tritiumdisposal.com or fax to: 614-863-0622.
Make sure to include your contact info if you have not already been assigned a TritiumDisposal.com account rep.

 **JOHN MUIR**
HEALTH
Concord Campus
2540 East Street
Concord, CA 94520-1906


CERTIFIED MAIL™



12 JUN 2013 11:51

US POSTAGE **\$06.11**
ZIP 94520

NIXIE 205554040-1N 06/22/13
RETURN TO SENDER
INSUFFICIENT ADDRESS
UNABLE TO FORWARD
RETURN TO SENDER



Director, Office of Federal and State Materials
and Environmental Management Programs
ATTN: Document Control Desk/GLTS
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555-0001

20852

205550001



8/5/13 To whom it may concern,
this letter was returned to us. We have enclosed
the original form for submission.