

Rio Tinto

Kennecott Uranium Company
42 Miles NW of Rawlins
P.O. Box 1500
Rawlins, WY 82301-1500
USA
T +1 (307) 328 1476
F +1 (307) 324 4925

28 February 2013

Mr. Andrew Persinko, Deputy Director
Division of Waste Management and Environmental Protection
Office of Federal and State Materials and Environmental Management Programs
U.S. Nuclear Regulatory Commission
11545 Rockville Pike
Rockville, MD 20852-2738

Dear Mr. Persinko:

SUBJECT: Sweetwater Uranium Project – Docket Number 40-8584 – Source Material License #SUA-1350, License Condition 12.3 – Required Reporting

Enclosed is one CD-ROM containing the following reports pertaining to Kennecott Uranium Company's Source Material License #SUA-1350:

- Semiannual 10 CFR 40.65 Report (Airborne Effluents) – summarizes the results of air and ambient gamma monitoring for the site;
- Annual ALARA Audit – summarizes the results of the annual ALARA audit for the facility, contains data pertinent to the facility's radiation safety program and includes the Annual Safety and Environmental Review Panel (SERP) Report;
- Annual Land Use Survey – summarizes land use in the vicinity of the Sweetwater Uranium Project.
- Annual Corrective Action Program Review – summarizes all monitoring and mitigation efforts in the area of the tailings cell under the groundwater corrective action program and contains the Groundwater Monitoring Report required annually as per License Condition 12.3;

All of these reports are being submitted together as originally requested by Louis Carson during his inspection of the facility in 1995. It was later discussed with Charlotte Abrams in telephone conversations on January 30, 1997 and February 5, 1998. She stated that these reports could all be submitted together within the sixty-day time period following January 1 of each year allowed for the 40.65 report. This single submittal procedure was incorporated into the facility's new performance based operating license in License Condition 12.3. In addition, only the most recent sample results for the tailings impoundment monitor wells are being submitted, as per a request made by Bob Evans during his inspection on July 8, 1997.

Kennecott Uranium Company has examined the data included in the 40.65 report containing the air and ambient gamma monitoring data for the site and has concluded that the dose does not exceed the 100-mrem per year dose limit. A copy of the calculation sheet as well as an explanation of the calculation method is included. This is being done at the request of Elaine Brummett of your staff in an email dated September 7, 2001. This issue was further discussed with James Webb of your staff in a telephone conversation, an email dated Wednesday, January 19, 2011, and a reply dated February 28, 2011. This discussion was in response to the presentation given by Duane Schmidt at the meeting between Nuclear Regulatory Commission (NRC) staff and members of the uranium recovery industry on January 12, 2011 in Denver, Colorado. Should you have any questions, please do not hesitate to contact me at (307) 328-1476.

Sincerely,


Oscar A. Paulson
Facility Supervisor

cc: James Webb – Project Manager (2)
Director – NRC DRSS – Region IV (w/o enc.)
Rich Atkinson – Rio Tinto America, Inc.