NRC FORM 591M PART 1 U.S. NUCLEAR REGULATORY COMMISSIO (10-2011)* 10 CFR 2.201					
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION					
1. LICENSEE/LOCATION INSPECTED:		2. NRC/REGIONAL OFFICE			
C.T. Radiology Complex & MRI Institute State Road #2, Km. 11.7 Bayamón, PR 00960-2727		U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713			
REPORT NUMBER(S) 2013-001					
3. DOCKET NUMBER(S) 030-08264	-	4. LICENSE NUMBER(S) 52-14931-01		5. DATE(S) OF INSPECTION 8/14/2013	
LICENSEE:	52-14931-01	32-14931-01		6/14/2013	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X					
Statement of Corrective Actions					
I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.					
Title	Printed Name		Signature	Date	
LICENSEE'S REPRESENTATIVE					
NRC INSPECTOR	Tara L. Weidner		/RA/	8/14/2013	
BRANCH CHIEF	James P. Dwyer		/RA/	8/26/2013	
*NRC FORM 591M PART 1 (10-2011) (RI Rev. 06/04/2012) G:\WordDocs\Current\Insp Record\R52-14931-01.2013-001.591M-Part1.doc SUNSI Review Completed By: /RA / TLWeidner X Public X Non-Sensitive					