

# UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION II 245 PEACHTREE CENTER AVENUE NE, SUITE 1200 ATLANTA, GEORGIA 30303-1257

August 29, 2013

Mr. Dennis R. Madison Vice President Southern Nuclear Operating Company, Inc. Edwin I. Hatch Nuclear Plant 11028 Hatch Parkway North Baxley, GA 31513

SUBJECT: ERRATA - EDWIN I. HATCH NUCLEAR PLANT - NRC SECURITY INSPECTION

REPORT 05000321/2012404, 05000366/2012404, and 072000036/2012401

Dear Mr. Madison:

On December 6, 2012, the U. S. Nuclear Regulatory Commission (NRC) issued the subject inspection report for the Edwin I. Hatch Nuclear Plant, Units 1 and 2. In reviewing this report, it was noted that the docket number associated with the Independent Spent Fuel Storage Installation (ISFSI) security inspection was inadvertently omitted from that inspection report. Accordingly, we are providing a revised version of Inspection Report 05000321/2012404, 05000366/2012404, and 072000036/2012401 that documents the change.

In accordance with Title 10 of the *Code of Federal Regulations* (10 CFR) 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room, or from the Publicly Available Records (PARS) component of NRC's Agencywide Documents Access and Management System (ADAMS), which is accessible from the NRC Website at <a href="http://www.nrc.gov/reading-rm/adams.html">http://www.nrc.gov/reading-rm/adams.html</a> (the Public Electronic Reading Room). However, because of the security-related concerns contained in the Enclosure, and in accordance with 10 CFR 2.390, a copy of this letter's Enclosure will not be available for public inspection.

Enclosure(s) transmitted herewith contain(s) SUNSI. When separated from Enclosure(s), this transmittal document is decontrolled.

D. Madison

I apologize for any inconvenience this error may have caused. If you have any questions, please contact me at 404-997-4519.

2

Sincerely,

/RA/

Binoy Desai, Chief Plant Support Branch 2 Division of Reactor Safety

Docket Nos. 50-321, 50-366, and 72-036

License Nos. DPR-57 and NPF-5

Enclosure:

IR 05000321/2012404, 05000366/2012404,

-and 072000036/2012401

-w/Attachment: Supplementary Information (OUO)

cc: (See page 3 below)

D. Madison	2
I apologize for any inconvenience this error please contact me at 404-997-4519.	may have caused. If you have any questions,
	Sincerely,
	/RA/
	Binoy Desai, Chief Plant Support Branch 2 Division of Reactor Safety
Docket Nos. 50-321, 50-366, and 72-036 License Nos. DPR-57 and NPF-5	
Enclosure: IR 05000321/2012404, 05000366/2012404 -and 072000036/2012401 -w/Attachment: Supplementary Information	
cc: (See page 3)	
DISTRIBUTION: RidsNrrPMHatch Resource C. Evans, RII, EICS L. Douglas, RII, EICS M. Layton, NSIR R. Albert, NSIR S. Coker, NSIR RIDSNRRDIRS	

(ERRATA to ML12195A348)

PUBLIC (OUO removed)

□ PUBLICL	Y AVAILABLE (OUC	) removed)	NON-PUBLICLY	AVAILABLE 🗌 SE	ENSITIVE	☑ NON-SENSITIVE (OUO removed)				
ADAMS: X Yes	ACCESSION NUMBE	ER: ML1324	1A113	☑ SUNSI REVIEW COMPLETE ☑ FORM 665 ATTACHED						
OFFICE	RII:DRS/PSB2	RII:DRP/BR2	RII:DRS/PSB2							
SIGNATURE	JSC3	FJE	BBD							
NAME	J. Shehee	F. Ehrhardt	B. Desai							
DATE	8/ 28 /2013	8/ 28 /20103	8/ 29 /2013							
F-MAIL COPY	YES NO	YES NO	YES NO							

OFFICIAL RECORD COPY DOCUMENT NAME: G:\DRSII\PSBII\REACTORS\HATCH\REPORTS\2012\HATCH INSP PUBLIC REPORT 2012404 REV1.DOC

December 6, 2012

Mr. Dennis R. Madison Vice President Southern Nuclear Operating Company, Inc. Edwin I. Hatch Nuclear Plant 11028 Hatch Parkway North Baxley, GA 31513

SUBJECT: EDWIN I. HATCH NUCLEAR PLANT - NRC SECURITY INSPECTION REPORT

05000321/2012404, 05000366/2012404, AND 072000036/2012401

Dear Mr. Madison,

On November 8, 2012, the U. S. Nuclear Regulatory Commission (NRC) completed a security baseline inspection at Edwin I. Hatch Nuclear Plant, Units 1 and 2. The inspection covered one or more of the key attributes of the security cornerstone of the NRC's Reactor Oversight Process. The enclosed report documents the inspection results, which were discussed with Mr. D. Vineyard and members of your staff.

This inspection examined activities conducted under your license as they relate to security and compliance with the Commission's rules and regulations, and with the conditions of your license. The inspector reviewed selected procedures and records, observed activities, and interviewed personnel.

Based on the results of this inspection, no findings were identified.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's Agency wide Document Access and Management system, ADAMS. ADAMS is accessible from the NRC Website at <a href="http://www.nrc.gov/reading-rm/adams.html">http://www.nrc.gov/reading-rm/adams.html</a> (the Public Electronic Reading Room). However, because of the security-related concerns contained in the enclosure, and in accordance with 10 CFR 2.390, a copy of this letter's enclosure will not be available for public inspection.

However, the material enclosed herewith contains Security-Related Information in accordance with 10 CFR 2.390 (d)(1) and its disclosure to unauthorized individuals could present a security vulnerability. Therefore, the materials in the enclosure will not be made available electronically

Enclosure(s) transmitted herewith contain(s) SUNSI. When separated from Enclosure(s), this transmittal document is decontrolled.

SNC 2

for public inspection in the NRC Public Document Room or from the PARS component of NRC's ADAM. If you choose to provide a response and Security-Related Information is necessary to provide an acceptable response, please mark your entire response "Security Related Information – Withhold form public disclosure under 10 CFR 2.390" in accordance with 10 CFR 2.390 (d)(1) and follow the instructions for withhold10 CFR 2.390 (b)(1). In accordance with 10 CFR 2.390(b)(1)(ii), the NRC is waiving the affidavit requirements for your response.

Sincerely,

/RA/

Binoy Desai, Chief Plant Support Branch 2 Division of Reactor Safety

Docket No. 50-321, 50-366, and 72-036

License No. DPR-57, NPF-5

#### Enclosure:

IR 05000321/2012404, 05000366/2012404,

and 072000036/2012401

-w/Attachment: Supplementary Information (OUO)

cc: (See page 3)

Enclosure(s) transmitted herewith contain(s) SUNSI. When separated from enclosure(s), this transmittal document is decontrolled.

SNC 2

for public inspection in the NRC Public Document Room or from the PARS component of NRC's ADAM. If you choose to provide a response and Security-Related Information is necessary to provide an acceptable response, please mark your entire response "Security Related Information – Withhold form public disclosure under 10 CFR 2.390" in accordance with 10 CFR 2.390 (d)(1) and follow the instructions for withhold10 CFR 2.390 (b)(1). In accordance with 10 CFR 2.390(b)(1)(ii), the NRC is waiving the affidavit requirements for your response.

Sincerely,

/RA/

Binoy Desai, Chief Plant Support Branch 2 Division of Reactor Safety

Docket No. 50-321, 50-366, and 72-036

License No. DPR-57, NPF-5

Enclosure:

IR 05000321/2012404, 05000366/2012404,

and 072000036/2012401

w/Attachment: Supplementary Information (OUO)

cc: (See page 3)

Distribution:

RidsNrrPMSurry Resource

C. Evans, RII, ÉICS

L. Douglas, RII, EICS

M. Layton, NSIR

R. Albert, NSIR

S. Coker, NSIR

**RIDSNRRDIRS** 

PUBLIC (w/o OUO)

□ PUBLICLY AVAILABLE X NON-PUBLICLY AVAILABLE X SENSITIVE □ NON-SENSITIVE

ADAMS: X Yes ACCESSION NUMBER: ML12195A348 X SUNSI REVIEW COMPLETE X FORM 665 ATTACHED

OFFICE	RII:DRS/PS	SB2	RII:DRS/F	PSB2	RII: DRS	S/PSB2	RII: DR	S/PSB2	RII: DRS	S/PSB2	RII: DRS/I	PSB2	RII: DRP/BR5B
SIGNATURE	RA/AR Via Email		RA/ Ema	il	RA/		RA/AT \ Email	Via	RA/RP \ Email	/ia	RA/BD		RA/GM Via Email
NAME	J. Wallo						Liliali		Liliali		B. Desai		G. McCoy
DATE	11/XX/20	)12									11/XX/2	2012	11/XX/2012
E-MAIL COPY?	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NC	

OFFICIAL RECORD COPY DOCUMENT NAME: G:\DRSII\PSBII\REACTORS\HATCH\REPORTS\2012\HATCH INSP PUBLIC REPORT 2012404 REV1.DOC

Enclosure(s) transmitted herewith contain(s) SUNSI. When separated from enclosure(s), this transmittal document is decontrolled.

D. Madison 3

CC:

Keith Wooten
Project Manager
Nuclear Fleet Security
Southern Nuclear Operating Company, Inc.
40 Inverness Center Parkway
Birmingham, AL 35242

David Burford
Manager
Nuclear Fleet Security
Southern Nuclear Operating Company, Inc.
40 Inverness Center Parkway
Birmingham, AL 35242

L. B. Hogg Nuclear Licensing Southern Nuclear Operating Company, Inc. 40 Inverness Center Parkway Birmingham, AL 35242

Jonathan M. Merritt Site Security Manager Edwin I. Hatch Nuclear Plant 11028 Hatch Parkway North Baxley, GA 31513