

# BED BATH & BEYOND



## Corporate Office

650 Liberty Avenue  
Union, NJ 07083  
908/688-0888

9-6-13

Director  
Office of Federal and State Materials and Environmental Management Programs  
ATTN: GLTS  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555-0001

**Re: Transfer of Tritium Exit Signs  
Bed Bath & Beyond Store #1006, Walker, MI**

Dear Sir or Madam:

Pursuant to Michigan regulation, Bed Bath & Beyond Inc. ("BBB") provides this notice that on date, August 26, 2013, BBB transferred the self-luminous exit signs listed on the attached table from BBB Store #1006 located at Green Ridge Square, 3410 Alpine NW, Walker, MI 49544 to Shield Source Inc., Attn: Taylor Perry, 925-211C Airport Road, Cavan Monaghan, ON K9J0E7 with license number CNSC # IL-A1-4790.0/2014.. For each sign, the manufacturer name, model number, serial number, manufacture date, and original curie content are indicated on the attached tables.

Please contact me at 908-855-4294 if you have any questions regarding this letter or the attached report.

Sincerely,

9/6/2013

**Jim O'Connor**  
Bed Bath & Beyond Inc.  
Vice President - Loss Prevention and Safety

## Serial Number Spreadsheet (Box Contents)

Store #: 1006 Address: 3410 Alpine Ave. NW City, State: Walker, MI

- Fill out this form for each tritium exit sign going into a box
- Do not exceed 99 curies per box. Seal the box according to the packaging instructions
- FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store
- FAX to CB&I at 225-987-3228 BEFORE you leave the store

RMA #: <u>9764A</u> Box <u>1</u> of <u>5</u> Weight of Box: <u>28</u> Total Curies in this box: <u>80.5</u>	<b>Do NOT exceed 99 curies per box</b>  8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box.  Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at <u>less than 100 curies each box</u> )
----------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)
1	SLC	9/2004	SLX-60	287460	11.5
2	SLC	9/2004	SLX-60	287455	11.5
3	SLC	9/2004	SLX-60	287459	11.5
4	SLC	9/2004	SLX-60	287456	11.5
5	SLC	9/2004	SLX-60	287441	11.5
6	SLC	9/2004	SLX-60	287454	11.5
7	SLC	9/2004	SLX-60	287452	11.5
8					
9					
10					

## Serial Number Spreadsheet (Box Contents)

Store #: 1006 Address: 3410 Alpine Ave. NW City, State: Walker, MI

- Fill out this form for each tritium exit sign going into a box
- Do not exceed 99 curies per box. Seal the box according to the packaging instructions
- FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store**
- FAX to CB&I at 225-987-3228 BEFORE you leave the store**

RMA #: <u>9764PA</u> Box <u>2</u> of <u>5</u> Weight of Box: <u>24</u> Total Curies in this box: <u>69</u>	<b>Do NOT exceed 99 curies per box</b> 8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box. Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at <u>less than</u> 100 curies each box)
---------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)
1	SLC	9/2004	SLX-60	287449	11.5
2	SLC	9/2004	SLX-60	287444	11.5
3	SLC	9/2004	SLX-60	287446	11.5
4	SLC	9/2004	SLX-60	287447	11.5
5	SLC	9/2004	SLX-60	287453	11.5
6	SLC	9/2004	SLX-60	287445	11.5
7					
8					
9					
10					

## Serial Number Spreadsheet (Box Contents)

Store #: 1006 Address: 3410 Alpine Ave NW City, State: Walker, MI

- Fill out this form for each tritium exit sign going into a box
- Do not exceed 99 curies per box. Seal the box according to the packaging instructions
- FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store**
- FAX to CB&I at 225-987-3228 BEFORE you leave the store**

RMA #: <u>9764 PA</u> Box <u>3</u> of <u>5</u> Weight of Box: <u>24</u> Total Curies in this box: <u>69</u>	<b>Do NOT exceed 99 curies per box</b>  8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box.  Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at <u>less than 100 curies each box</u> )
----------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)
1	SLC	9/2004	SLX-60	287458	11.5
2	SLC	9/2004	SLX-60	287442	11.5
3	SLC	9/2004	SLX-60	287451	11.5
4	SLC	9/2004	SLX-60	287448	11.5
5	SLC	9/2004	SLX-60	287457	11.5
6	SLC	9/2004	SLX-60	287450	11.5
7					
8					
9					
10					

## Serial Number Spreadsheet (Box Contents)

Store #: 1006 Address: 3410 Alpine Ave NW City, State: Walker, MI

- Fill out this form for each tritium exit sign going into a box
- Do not exceed 99 curies per box. Seal the box according to the packaging instructions
- FAX to Taylor Perry at Isolite 610-296-8952 BEFORE** you leave the store
- FAX to CB&I at 225-987-3228 BEFORE** you leave the store

RMA #: <u>9764PA</u> Box <u>4</u> of <u>5</u> Weight of Box: <u>24</u> Total Curies in this box: <u>69</u>	<b>Do NOT exceed 99 curies per box</b> 8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box. Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at <u>less than</u> 100 curies each box)
---------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)
1	SLC	9/2004	SLX-60	287461	11.5
2	SLC	9/2004	SLX-60	287465	11.5
3	SLC	9/2004	SLX-60	287443	11.5
4	SLC	9/2004	SLX-60	287463	11.5
5	SLC	9/2004	SLX-60	287464	11.5
6	SLC	9/2004	SLX-60	287466	11.5
7					
8					
9					
10					

## Serial Number Spreadsheet (Box Contents)

Store #: 1006 Address: 3410 Alpine Ave NW City, State: Walker, MI

- Fill out this form for each tritium exit sign going into a box
- Do not exceed 99 curies per box. Seal the box according to the packaging instructions
- FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store
- FAX to CB&I at 225-987-3228 BEFORE you leave the store

RMA #: <u>9764PA-D</u> Box <u>5</u> of <u>5</u> Weight of Box: <u>4</u> Total Curies in this box: <u>11.5</u>	<b>Do NOT exceed 99 curies per box</b> 8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box. Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at <u>less than 100 curies each box</u> )
------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)
1	SLC	9/2004	SLX-600	287462	11.5
2					
3					
4					
5					
6					
7					
8					
9					
10					

# BED BATH & BEYOND

**Harmon.**  
**STORES, INC.**  
A Bed Bath & Beyond Subsidiary



## Corporate Office

650 Liberty Avenue  
Union, NJ 07083  
908/688-0888

9-6-13

Director  
Office of Federal and State Materials and Environmental Management Programs  
ATTN: GLTS  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555-0001

**Re: Transfer of Tritium Exit Signs  
Bed Bath & Beyond Store #1112, Rutland, VT**

Dear Sir or Madam:

Pursuant to Vermont regulation, Bed Bath & Beyond Inc. ("BBB") provides this notice that on August 27, 2013, BBB transferred the self-luminous exit signs listed on the attached table from BBB Store #1112 located at 322 Route 7 South, Rutland, VT 05701, to Shield Source Inc., Attn: Taylor Perry, 925-211C Airport Road, Cavan Monaghan, ON K9J0E7 with license number CNSC # IL-A1-4790.0/2014.. For each sign, the manufacturer name, model number, serial number, manufacture date, and original curie content are indicated on the attached tables.

Please contact me at 908-855-4294 if you have any questions regarding this letter or the attached report.

Sincerely,

*James O'Connor 9/6/2013*

**Jim O'Connor**  
Bed Bath & Beyond Inc.  
Vice President - Loss Prevention and Safety

# Serial Number Spreadsheet (Box Contents)

Store #: 1112 Address: 322 Route 7 South City, State: Rutland, VT

- Fill out this form for each tritium exit sign going into a box
- Do not exceed 99 curies per box. Seal the box according to the packaging instructions
- FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store
- FAX to CB&I at 225-987-3228 BEFORE you leave the store

RMA #: <u>9796PA</u> Box <u>1</u> of <u>2</u> Weight of Box: <u>32 lbs.</u> Total Curies in this box: <u>92</u>	<b>Do NOT exceed 99 curies per box</b>  8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box.  Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at <u>less than 100 curies each box</u> )
--------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)
1	<u>Safety Light Corp(SLC)</u>	<u>6/06</u>	<u>SLX-60</u>	<u>373650</u>	<u>11.5</u>
2	<u>SLC</u>	<u>6/06</u>	<u>SLX-60</u>	<u>373647</u>	<u>11.5</u>
3	<u>SLC</u>	<u>6/06</u>	<u>SLX-60</u>	<u>373657</u>	<u>11.5</u>
4	<u>SLC</u>	<u>6/06</u>	<u>SLX-60</u>	<u>373646</u>	<u>11.5</u>
5	<u>SLC</u>	<u>6/06</u>	<u>SLX-60</u>	<u>373651</u>	<u>11.5</u>
6	<u>SLC</u>	<u>6/06</u>	<u>SLX-60</u>	<u>373656</u>	<u>11.5</u>
7	<u>SLC</u>	<u>6/06</u>	<u>SLX-60</u>	<u>373658</u>	<u>11.5</u>
8	<u>SLC</u>	<u>6/06</u>	<u>SLX-60</u>	<u>373648</u>	<u>11.5</u>
9					
10					



## Serial Number Spreadsheet (Box Contents)

Store #: 1112 Address: 322 Route 7 South City, State: Rutland, VT

- Fill out this form for each tritium exit sign going into a box
- Do not exceed 99 curies per box. Seal the box according to the packaging instructions
- FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store
- FAX to CB&I at 225-987-3228 BEFORE you leave the store

RMA #: <u>9796PA</u> Box <u>2</u> of <u>2</u> Weight of Box: <u>20 lbs.</u> Total Curies in this box: <u>57.5</u>	<b>Do NOT exceed 99 curies per box</b>  8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box.  Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at <u>less than</u> 100 curies each box)
----------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)
1	SLC	6/06	SLX-60	373649	11.5
2	SLC	6/06	SLX-60	373654	11.5
3	SLC	6/06	SLX-60	373655	11.5
4	SLC	6/06	SLX-60	373652	11.5
5	SLC	6/06	SLX-60	373653	11.5
6					
7					
8					
9					
10					

# BED BATH & BEYOND

**Harmon.**  
**STORES, INC.**  
A Bed Bath & Beyond Subsidiary



## Corporate Office

650 Liberty Avenue  
Union, NJ 07083  
908/688-0888

9-6-13

Director  
Office of Federal and State Materials and Environmental Management Programs  
ATTN: GLTS  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555-0001  
Director

**Re: Transfer of Tritium Exit Signs  
Bed Bath & Beyond Store #1175, Anchorage, AK**

Dear Sir or Madam:

Pursuant to Alaska regulation, Bed Bath & Beyond Inc. ("BBB") provides this notice that on August 30, 2013, BBB transferred the self-luminous exit signs listed on the attached table from BBB Store #1175 located at 601 E Dimond Blvd, Anchorage, AK 99515, to Shield Source Inc., Attn: Taylor Perry, 925-211C Airport Road, Cavan Monaghan, ON K9J0E7 with license number CNSC # IL-A1-4790.0/2014. For each sign, the manufacturer name, model number, serial number, manufacture date, and original curie content are indicated on the attached tables.

Please contact me at 908-855-4294 if you have any questions regarding this letter or the attached report.

Sincerely,

James O'Connor 9/6/2013

---

**Jim O'Connor**  
Bed Bath & Beyond Inc.  
Vice President - Loss Prevention and Safety

## Serial Number Spreadsheet (Box Contents)

Store #: 1175 Address: 601 E. Diamond Blvd City, State: Anchorage, AK

- Fill out this form for each tritium exit sign going into a box
- Do not exceed 99 curies per box. Seal the box according to the packaging instructions
- FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store
- FAX to CB&I at 225-987-3228 BEFORE you leave the store

RMA #: <u>4805 PA</u> Box <u>4</u> of <u>4</u> Weight of Box: <u>32 lbs</u> Total Curies in this box: <u>92</u>	<b>Do NOT exceed 99 curies per box</b> 8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box. Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at <u>less than 100 curies each box</u> )
--------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)
1	Safety Light Corp	12/2006	SLX-60	394023	11.5
2	Safety Light Corp	11/2006	SLX-60	391627	11.5
3	Safety Light Corp	12/2006	SLX-60	394022	11.5
4	Safety Light Corp	12/2006	SLX-60	394021	11.5
5	Safety Light Corp	12/2006	SLX-60	394015	11.5
6	Safety Light Corp	12/2006	SLX-60	394000	11.5
7	Safety Light Corp	12/2006	SLX-60	393998	11.5
8	Safety Light Corp	12/2006	SLX-60	394140	11.5
9					
10					

## Serial Number Spreadsheet (Box Contents)

Store #: 1175 Address: 601 E. Diamond Blvd City, State: Anchorage, AK

- Fill out this form for each tritium exit sign going into a box
- Do not exceed 99 curies per box. Seal the box according to the packaging instructions
- FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store
- FAX to CB&I at 225-987-3228 BEFORE you leave the store

RMA #: <u>9805 PA</u> Box <u>2</u> of <u>4</u> Weight of Box: <u>28</u> Total Curies in this box: <u>80.5</u>	<b>Do NOT exceed 99 curies per box</b> 8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box. Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at <u>less than</u> 100 curies each box)
------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)
1	Safety Light Corp	12/2006	SLX-60	394009	11.5
2	Safety Light Corp	12/2006	SLX-60	394010	11.5
3	Safety Light Corp	11/2006	SLX-60	391625	11.5
4	Safety Light Corp	12/2006	SLX-60	394019	11.5
5	Safety Light Corp	12/2006	SLX-60	394027	11.5
6	Safety Light Corp	12/2006	SLX-60	394024	11.5
7	Safety Light Corp	12/2006	SLX-60	394016	11.5
8					
9					
10					

## Serial Number Spreadsheet (Box Contents)

Store #: 1175 Address: 601 E. Dimond Blvd City, State: Anchorage, AK

- Fill out this form for each tritium exit sign going into a box
- Do not exceed 99 curies per box. Seal the box according to the packaging instructions
- FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store**
- FAX to CB&I at 225-987-3228 BEFORE you leave the store**

<p>RMA #: <u>9805PA</u></p> <p>Box <u>3</u> of <u>4</u></p> <p>Weight of Box: <u>28 lbs</u></p> <p>Total Curies in this box: <u>80.5</u></p>	<p><b>Do NOT exceed 99 curies per box</b></p> <p>8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box.</p> <p>Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at <u>less than 100 curies each box</u>)</p>
----------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)
1	Safety Light Corp	12/2006	SLX-60	394003	11.5
2	Safety Light Corp	12/2006	SLX-60	394001	11.5
3	Safety Light Corp	11/2006	SLX-60	391626	11.5
4	Safety Light Corp	12/2006	SLX-60	394011	11.5
5	Safety Light Corp	12/2006	SLX-60	394017	11.5
6	Safety Light Corp	12/2006	SLX-60	394005	11.5
7	Safety Light Corp	12/2006	SLX-60	394004	11.5
8					
9					
10					

## Serial Number Spreadsheet (Box Contents)

Store #: 1175 Address: 601 E. Diamond Blvd City, State: Anchorage, AK

- Fill out this form for each tritium exit sign going into a box
- Do not exceed 99 curies per box. Seal the box according to the packaging instructions
- FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store
- FAX to CB&I at 225-987-3228 BEFORE you leave the store

RMA #: <u>9805PA</u> Box <u>4</u> of <u>4</u> Weight of Box: <u>28 lbs</u> Total Curies in this box: <u>80.5</u>	<b>Do NOT exceed 99 curies per box</b> 8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box. Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at <u>less than</u> 100 curies each box)
---------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)
1	Safety Light Corp	12/2006	SLX-60	394 002	11.5
2	Safety Light Corp	12/2006	SLX-60	394 008	11.5
3	Safety Light Corp	12/2006	SLX-60	394 018	11.5
4	Safety Light Corp	12/2006	SLX-60	394 006	11.5
5	Safety Light Corp	12/2006	SLX-60	394 007	11.5
6	Safety Light Corp	12/2006	SLX-60	394 013	11.5
7	Safety Light Corp	12/2006	SLX-60	394 012	11.5
8					
9					
10					

# BED BATH & BEYOND

**Harmon**  
STORES, INC.  
A Bed Bath & Beyond Subsidiary



**Corporate Office**  
650 Liberty Avenue  
Union, NJ 07083  
908/688-0888

9-6-13

Director  
Office of Federal and State Materials and Environmental Management Programs  
ATTN: GLTS  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555-0001

**Re: Transfer of Tritium Exit Signs  
Bed Bath & Beyond Store #1114, Pocatello, ID**

Dear Sir or Madam:

Pursuant to Idaho regulation, Bed Bath & Beyond Inc. ("BBB") provides this notice that on August 30, 2013, BBB transferred the self-luminous exit signs listed on the attached table from BBB Store #1114 located at 1732 Hurley Drive, Pocatello, ID 83202, to Shield Source Inc., Attn: Taylor Perry, 925-211C Airport Road, Cavan Monaghan, ON K9J0E7 with license number CNSC # IL-A1-4790.0/2014. For each sign, the manufacturer name, model number, serial number, manufacture date, and original curie content are indicated on the attached tables.

Please contact me at 908-855-4294 if you have any questions regarding this letter or the attached report.

Sincerely,

*Jim O'Connor 9/6/2013*

---

**Jim O'Connor**  
Bed Bath & Beyond Inc.  
Vice President - Loss Prevention and Safety

## Serial Number Spreadsheet (Box Contents)

Store #: 1114 Address: 1732 Hurley Drive City, State: Pocatello, ID

- Fill out this form for each tritium exit sign going into a box
- Do not exceed 99 curies per box. Seal the box according to the packaging instructions
- FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store
- FAX to CB&I at 225-987-3228 BEFORE you leave the store

RMA #: <u>9853PA</u> Box <u>1</u> of <u>2</u> Weight of Box: <u>28</u> Total Curies in this box: <u>80.5</u>	<b>Do NOT exceed 99 curies per box</b> 8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box. Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at less than 100 curies each box)
-----------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)
1	Safety Light Corp	6/2006	SLX-60	375915	11.5
2	Safety Light Corp	6/2006	SLX-60	375911	11.5
3	Safety Light Corp	6/2006	SLX-60	375910	11.5
4	Safety Light Corp	6/2006	SLX-60	375909	11.5
5	Safety Light Corp	6/2006	SLX-60	375906	11.5
6	Safety Light Corp	6/2006	SLX-60	375914	11.5
7	Safety Light Corp	6/2006	SLX-60	375907	11.5
8					
9					
10					



## Serial Number Spreadsheet (Box Contents)

Store #: 1114 Address: 1732 Hurley Drive City, State: Pocatello, ID

- Fill out this form for each tritium exit sign going into a box
- Do not exceed 99 curies per box. Seal the box according to the packaging instructions
- FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store
- FAX to CB&I at 225-987-3228 BEFORE you leave the store

RMA #: <u>9853PA</u> Box <u>2</u> of <u>2</u> Weight of Box: <u>28</u> Total Curies In this box: <u>80.5</u>	<b>Do NOT exceed 99 curies per box</b> 8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box. Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at <u>less than</u> 100 curies each box)
-----------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)
1	Safety Light Corp	6/2006	SLX-60	375912	11.5
2	Safety Light Corp	6/2006	SLX-60	375925	11.5
3	Safety Light Corp	6/2006	SLX-60	375917	11.5
4	Safety Light Corp	6/2006	SLX-60	375916	11.5
5	Safety Light Corp	6/2006	SLX-60	375918	11.5
6	Safety Light Corp	6/2006	SLX-60	375924	11.5
7	Safety Light Corp	6/2006	SLX-60	375913	11.5
8					
9					
10					

# BED BATH & BEYOND

**Harmon.**  
**STORES, INC.**  
A Bed Bath & Beyond Subsidiary



## Corporate Office

650 Liberty Avenue  
Union, NJ 07083  
908/688-0888

9-6-13

Director  
Office of Federal and State Materials and Environmental Management Programs  
ATTN: GLTS  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555-0001

**Re: Transfer of Tritium Exit Signs  
Bed Bath & Beyond Store #1197, Anchorage, AK**

Dear Sir or Madam:

Pursuant to Alaska regulation, Bed Bath & Beyond Inc. ("BBB") provides this notice that on August 19, 2013, BBB transferred the self-luminous exit signs listed on the attached table from BBB Store #1197 located at 3090 Mountain View Dr., Suite 120, Anchorage, Alaska 99501, to Shield Source Inc., Attn: Taylor Perry, 925-211C Airport Road, Cavan Monaghan, ON K9J0E7 with license number CNSC # IL-A1-4790.0/2014. For each sign, the manufacturer name, model number, serial number, manufacture date, and original curie content are indicated on the attached tables.

Please contact me at 908-855-4294 if you have any questions regarding this letter or the attached report.

Sincerely,

*James O'Connor 9/6/2013*

---

**Jim O'Connor**  
Bed Bath & Beyond Inc.  
Vice President - Loss Prevention and Safety

## Serial Number Spreadsheet (Box Contents)

Store #: 1197 Address: 3090 Mountain View Drive, Suite 120 City, State: Anchorage, AK

- Fill out this form for each tritium exit sign going into a box
- Do not exceed 99 curies per box. Seal the box according to the packaging instructions
- FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store
- FAX to CB&I at 225-987-3228 BEFORE you leave the store

RMA #: <u>9804PA</u> Box <u>1</u> of <u>2</u> Weight of Box: <u>28 lbs</u> Total Curies in this box: <u>80.5</u>	<b>Do NOT exceed 99 curies per box</b> 8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box. Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at less than 100 curies each box)
---------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)
1	Safety light corp	9/2007	SLX-60	429223	11.5
2	Safety light corp	9/2007	SLX-60	429230	11.5
3	Safety light corp	9/2007	SLX-60	429229	11.5
4	Safety light corp	9/2007	SLX-60	429220	11.5
5	Safety light corp	9/2007	SLX-60	429224	11.5
6	Safety light corp	9/2007	SLX-60	429225	11.5
7	Safety light corp	9/2007	SLX-60	429228	11.5
8					
9					
10					

## Serial Number Spreadsheet (Box Contents)

Store #: 1197 Address: 3090 Mountain View Drive, Suite 120 City, State: Anchorage, AK

- Fill out this form for each tritium exit sign going into a box
- Do not exceed 99 curies per box. Seal the box according to the packaging instructions
- FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store
- FAX to Shaw at 225-987-3228 BEFORE you leave the store

RMA #: <u>9804 PA</u> Box <u>2</u> of <u>2</u> Weight of Box: <u>24 lbs</u> Total Curies in this box: <u>69</u>	<b>Do NOT exceed 99 curies per box</b>  8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box.  Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at <u>less than</u> 100 curies each box)
--------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)
	Safety light corp	9/2007	SLX-60	429222	11.5
2	Safety light corp	9/2007	SLX-60	429231	11.5
3	Safety light corp	9/2007	SLX-60	429226	11.5
4	Safety light corp	9/2007	SLX-60	429232	11.5
5	Safety light corp	9/2007	SLX-60	429227	11.5
6	Safety light corp	9/2007	SLX-60	429221	11.5
7					
8					
9					
10					

# BED BATH & BEYOND

**Harmon.**  
**STORES, INC.**  
A Bed Bath & Beyond Subsidiary



**Corporate Office**  
650 Liberty Avenue  
Union, NJ 07083  
908/688-0888

9-6-13

Director  
Office of Federal and State Materials and Environmental Management Programs  
ATTN: GLTS  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555-0001

**Re: Transfer of Tritium Exit Signs  
Bed Bath & Beyond Store #1159, Nampa, ID**

Dear Sir or Madam:

Pursuant to Idaho regulation, Bed Bath & Beyond Inc. ("BBB") provides this notice that on August 29, 2013, BBB transferred the self-luminous exit signs listed on the attached table from BBB Store #1159 located at 16390 N Marketplace Blvd, Nampa, ID 83687, to Shield Source Inc., Attn: Taylor Perry, 925-211C Airport Road, Cavan Monaghan, ON K9J0E7 with license number CNSC # IL-A1-4790.0/2014. For each sign, the manufacturer name, model number, serial number, manufacture date, and original curie content are indicated on the attached tables.

Please contact me at 908-855-4294 if you have any questions regarding this letter or the attached report.

Sincerely,

*James O'Connor*

---

**Jim O'Connor**  
Bed Bath & Beyond Inc.  
Vice President - Loss Prevention and Safety

## Serial Number Spreadsheet (Box Contents)

Store #: 1159 Address: 16390 N. Market Blvd City, State: Nampa, ID

- Fill out this form for each tritium exit sign going into a box
- Do not exceed 99 curies per box. Seal the box according to the packaging instructions
- FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store
- FAX to CB&I at 225-987-3228 BEFORE you leave the store

RMA #: <u>9848 PA</u> Box <u>1</u> of <u>2</u> Weight of Box: <u>32 lbs</u> Total Curies in this box: <u>92</u>	<b>Do NOT exceed 99 curies per box</b> 8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box. Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at <u>less than</u> 100 curies each box)
--------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(CI or TBq amount) (Number of Curies)
1	Safety Light Corp	10/2006	SLX-60	388600	11.5
2	Safety Light Corp	10/2006	SLX-60	388606	11.5
3	Safety Light Corp	10/2006	SLX-60	388596	11.5
4	Safety Light Corp	10/2006	SLX-60	388599	11.5
5	Safety Light Corp	10/2006	SLX-60	388603	11.5
6	Safety Light Corp	10/2006	SLX-60	388597	11.5
7	Safety Light Corp	10/2006	SLX-60	388598	11.5
8	Safety Light Corp	10/2006	SLX-60	388601	11.5
9					
10					


## Serial Number Spreadsheet (Box Contents)

Store #: 1159 Address: 16390 W. Marketplace Blvd City, State: Nampa, ID

- Fill out this form for each tritium exit sign going into a box
- Do not exceed 99 curies per box. Seal the box according to the packaging instructions
- FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store
- FAX to CB&I at 225-987-3228 BEFORE you leave the store

RMA #: <u>4848PA</u> Box <u>2</u> of <u>2</u> Weight of Box: <u>32 lbs</u> Total Curies in this box: <u>92</u>	<b>Do NOT exceed 99 curies per box</b> 8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box. Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at <u>less than</u> 100 curies each box)
-------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(CI or TBq amount) (Number of Curies)
1	Safety light corp	9/2006	SLX-60	384385	11.5
2	Safety light corp	10/2006	SLX-60	388605	11.5
3	Safety light corp	9/2006	SLX-60	384387	11.5
4	Safety light corp	9/2006	SLX-60	384386	11.5
5	Safety light corp	10/2006	SLX-60	388604	11.5
6	Safety light corp	8/2006	SLX-60	387051	11.5
7	Safety light corp	10/2006	SLX-60	388607	11.5
8	Safety light corp	10/2006	SLX-60	388602	11.5
9					
10					



Extremely Urgent

Page 1 of 1

From: (908) 855-4611  
Leigh Strothers  
BED BATH  
650 Liberty Avenue  
Union, NJ 07083

Origin ID: CDWA



J13201306280326

Ship Date: 06SEP13  
ActWgt: 1.0 LB  
CAD: 1447625/INET3430

Delivery Address Bar Code



SHIP TO: (908) 855-4611

BILL SENDER

ATTN: GLTS


U.S. NUCLEAR REGULATORY COMMISSION  
OFF OF FED AND STATE MATERIALS

WASHINGTON, DC 20555

Ref # TES  
Invoice #  
PO #  
Dept # 918


MON - 09 SEP AA  
STANDARD OVERNIGHT

TRK# 7966 3103 4970  
0201



SA NSFA

20555  
DC-US  
IAD



51AG19256/1A9E

ments Only

le with the container and  
terms and conditions and  
the applicable FedEx  
the current FedEx Service  
ge.

Ex Express services,  
ions, go to **fedex.com**,  
x location.

Insert shipping  
document here.

RT 649 1 D  
4970  
09.09  
FZ