

October 9, 2013

MEMORANDUM TO:           SSD Case File 13-22  
                                  First Alert/BRK Brands, Inc.

                                  Sealed Source and Device Registration  
                                  NR-88282-D-801-E

FROM:                       John Jankovich **/RA/**  
                                  Licensing Branch, FSME/MSSA

                                  Tomas Herrera **/RA/**  
                                  Licensing Branch, FSME/MSSA

SUBJECT:                   No Checklist or Safety Evaluation Performed

By letter dated May 1, 2013, (ML13127A441) BRK, Inc. requested the inactivation of their sealed source registration certificate NR-0167-D-101-E.

Based on the information provided in the referenced letter above the registration certificate NR-1081-S-101-S was inactivated and inactive registration certificate NR-8282-D-801-E was issued to supercede it.

Production of the smoke detector did not cease. The inactivation was based on the the changes in the regulatory requirements in 10 CFR 3.14 and 10 CFR 32.26, issued on July 25, 2012, removing registration requirements for smoke detectors containing 1.0  $\mu$ Ci or less of Am-241. Consequently, the questions associated with inactivation, as listed in the applicable guidance document, NUREG-1556, Vol. 3, Rev. 1, Section 13.4 were not asked as not being applicable (i.e., the product was not discontinued).

For the same reason, no safety evaluation or the preparation of a checklist for sealed sources and devices was necessary.