J. Marinet	e d							
REG	ULATORY	INTOR	MATION	DISTRIBUTIO	N SYST	RID	S)	
ACCESSION NBR:83021 FACIL:50-361 San 0 50-362 San 0	nofre N	uclear	Stati	on, Unit 2,	Souther	noCali		
AUTHNAME BASKINAKAPA RECIPANAME KNIGHTONAGAWA	UCCTLTC	Callf NT AFF	ornia) ILIATI					
SUBJECT: Supply 830211 proposed change to Tech Spec 3/4.7.5 ne control room emergency aftr cleanup sys. Operating procedures to be nextered &/or nevised by 830313 to ensure door closure following toxic gas isolation signal.								
DISTRIBUTION CODE: TITLE: Licensing S								
NOTES: JeHanchett, 1cy PDR Documents, ELD Chandler 1cy. NRR Scaletti 1cy.								05000361
j:Hanchett.1		Docume	nts, ¤El	Dechandler.	lcy.			05000362
		COPIE		RECIPIENT		COPIES		
ID CODEXNAME NRR/DL/ADL				ID CODE/NAME		LITTR ENCL		
		1	~0 ≈0.	NRR LB3 BC ROOD,H.	01	1	⇒0 .1	
INTERNAL: ELDZHDS2		. 1 .	<i>*</i> 0	IEFILE		. 1.	. 1 -	
1EXDEP EPD	\$ 35.	- <b>-</b> *	. <b>1</b> .	IE/DEP/EPL	B 36	2 <b>3</b> ,	3	
NRR/DE/AEA		.1		NRR/DE/CEB		1	1	
NRR/DE/EQB		2	ž,	NRR/DE/GB		2	2	
NRR/DE/HGE		. 1	1	NRR/DE/MEB		. 1	.1	
NRR/DE/MTE		.1	1	NRR/DE/QAB		.1	i	
NRR/DE/SAB		. <b>1</b>	. 1 .	NRR/DE/SEB		1	. 1 -	
NRR/DHFS/H		1	1 -	NRR/DHFS/L		1	. 1 .	
NRR/DL/SSP	B-	. <b>1</b> .	~ <b>(</b> )	NRR/DSI/AE		1,	. 1.	
NRRZDSIZAS	B	.1.	. 1 .	NRR/DSI/CP		. 1 .	1	
NRR/DSI/CS		.1.	<b>1</b> C	NRR/DSI/IC	SB 16	<b>. 1</b> -	. 1	
NRR/DSI/ME		. 1 .	< <b>1</b> €	NRR/DSI/PS	B 19	. 1 .	1	
NRR/DSL/RA		. 1 -	њ 🛔 2	NRR/DSI/RS	B 23	. 1	1 -	
REG FILE		1 .	- <b>1</b> -	RGN5		23	2 <b>3</b> c	
RM/DDAMI/M	18	а • <b>Ц</b> х	× 0	•				
EXTERNAL: ACRS	41.	<b>:6</b> *	-6	BNL (AMDTS	ONLY)	. 1	. 1	
DMB/DSS (A		1 /	. 1	FEMA-REP D			. 1 .	
LPDR	03	1	". <b>1</b> 2	NRC PDR	50	1	. 1 :	
<b>NSIC</b>	-05	<b>1</b> •	*, <b>1</b> 2	NTIS	·	. 1	5 <b>1</b> -	
NOTES:		2 <b>3</b> -	3.					

· · · · · · · ·

TOTAL NUMBER OF COPIES REQUIRED: DITR SS ENCL 48

۰.

..

## Southern California Edison Company

P. O. BOX 800 2244 WALNUT GROVE AVENUE ROSEMEAD. CALIFORNIA 91770 February 16, 1983

K. P. BASKIN . MANAGER OF NUCLEAR ENGINEERING, SAFETY, AND LICENSING

1

Director, Office of Nuclear Reactor Regulation Attention: Mr. George W. Knighton, Branch Chief Licensing Branch No. 3 U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Gentlemen:

8302180291 830216 PDR ADOCK 05000361 P PDR

Subject: Docket Nos. 50-361 and 50-362 San Onofre Nuclear Generating Station Units 2 and 3

By letter dated February 11, 1983 SCE transmitted a proposed change to Units 2 and 3 Technical Specification 3/4.7.5, Control Room Emergency Air Cleanup System (CREACUS). The purpose of this letter is to supplement the information provided in that letter as requested by the NRC Staff in a meeting with SCE on February 16, 1983.

In order to confirm that control room boundary doors are closed following a toxic gas or radiological event, SCE will review, and revise as required, operating procedures to ensure the doors are closed following a toxic gas isolation signal or a control room isolation signal. Any required procedure revisions will be completed by March 13, 1983.

SCE will include revisions to the FSAR sections affected by the subject proposed Technical Specification change in the next amendment to the FSAR. This amendment is scheduled for issuance in April 1983. SCE will, of course, conduct a control room air test on both emergency ventilation system trains consistent with the requirements of Section e.4. of the subject Technical Specification.

In anticipation of NRC approval of the proposed technical specification change, SCE plans to conduct the control room air test Wednesday night, February 16, 1983. This will allow Unit 3 Startup to proceed without delay once NRC approval is received. NRC, Region V personnel have been notified and an NRC inspector will be present when the test is conducted.





TELEPHONE

(213) 572-1401

Mr. George W. Knighton

-2-

If you have any questions concerning the enclosed information please call me.

Very truly yours,

K.P. Baskin A. Filmer

cc: Harry Rood, NRC (To be opened by addressee only)