

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7905090277 DOC. DATE: 79/05/02 NOTARIZED: NO DOCKET #
 FACIL: 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2, SOUTHERN CALIFORN 05000361
 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3, SOUTHERN CALIFORN 05000362
 AUTH. NAME AUTHOR AFFILIATION
 MOORE, J. R. SOUTHERN CALIFORNIA EDISON CO.
 RECIP. NAME RECIPIENT AFFILIATION
 ENGELKERN, R. H. REGION 5, SAN FRANCISCO, OFFICE OF THE DIRECTOR

SUBJECT: 78 REVISED PIPE SUPPORT ASSEMBLY DRAWINGS HAVE YET TO BE
 ISSUED FOR USE IN CONSTR, BUT WILL BE BY 790504.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: CONSTRUCTION DEFICIENCY REPORT (10CFR50.55E).

NOTES: SEND ALL FSAR & ER AMENDS TO L. CHANDLER.

| | RECIPIENT ID CODE/NAME | COPIES LTR ENCL | RECIPIENT ID CODE/NAME | COPIES LTR ENCL |
|-----------|---------------------------|--------------------|---------------------------|--------------------|
| ACTION: | 14 PM <u>ROOD</u> | 1 | 15 BC <u>LWR #2</u> | 1 |
| | 20 LA <u>LWR #2</u> | 1 | 21 AD <u>VASSALLO</u> | 1 |
| INTERNAL: | 01 <u>REG FILE</u> | 1 | 02 NRC PDR | 1 |
| | 05 I&E | 2 | 07 EDO & STAFF | 1 |
| | 08 MPA | 1 | 09 DEPY DIR DPM | 1 |
| | 10 QAB | 1 | 11 STANDRDS DEV | 1 |
| | 12 JORDAN, E/IE | 1 | 13 FIELD COOR/IE | 1 |
| | 16 AD FOR ENGR | 1 | 17 AD PLANT SYS | 1 |
| | 17 AD REAC SFTY | 1 | 19 AD SYS/PROJ | 1 |
| | 22 DIR DPM | 1 | 23 OELD | 1 |
| EXTERNAL: | 03 LPOR | 1 | 04 NSIC | 1 |
| | 24 ACRS | 16 | | |

MAY 10 1979

TOTAL NUMBER OF COPIES REQUIRED: LTR 39 ENCL

0
39

MA 4
GD

Southern California Edison Company

P. O. BOX 800

2244 WALNUT GROVE AVENUE

ROSEMEAD, CALIFORNIA 91770

JACK B. MOORE
VICE PRESIDENT

May 2, 1979

TELEPHONE
213-572-2292

Mr. R. H. Engelken, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region V
Suite 202, Walnut Creek Plaza
1990 North California Blvd.
Walnut Creek, CA 94596

Dear Mr. Engelken:

Subject: Docket Nos. 50-361 and 50-362
San Onofre Nuclear Generating Station, Units 2 and 3

By letter dated January 8, 1979, we submitted a final report concerning a reportable condition in design of fillet welds for pipe supports designed in accordance with the ASME B&PV Code, Section III for San Onofre Units 2 and 3.

In the final report, we indicated that 304 pipe support assembly drawings had been revised to conform to Appendix XVII of the ASME B&PV Code, Section III. This statement should have indicated that the drawing changes had been prepared but not all changes had been issued for use in construction. As of the date of this letter, 78 drawing changes have yet to be issued. These changes will be issued by May 4, 1979.

If you have any further questions or require any additional information, please let us know.

Sincerely,



cc: John Davis (NRC-Acting Director I&E)
R. J. Pate (NRC-San Onofre 2 and 3)

7905090277

3019
5/10