

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8802230152	DOC.DATE: 88/01/31	NOTARIZED: NO	DOCKET #
FACIL:50-361 San Onofre Nuclear Station, Unit 2, Southern Californ			05000361
50-362 San Onofre Nuclear Station, Unit 3, Southern Californ			05000362

AUTH.NAME	AUTHOR AFFILIATION
MORGAN, H.E.	Southern California Edison Co.
RECIP.NAME	RECIPIENT AFFILIATION
	Document Control Branch (Document Control Desk)

SUBJECT: Forwards monthly operating repts for Jan 1988. Revised Unit 3  
monthly operating rept for Dec 1987 also encl.

DISTRIBUTION CODE: IE24D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 12H  
TITLE: Monthly Operating Report (per Tech Specs)

**NOTES:**

RECIPIENT		COPIES		RECIPIENT		COPIES	
ID CODE/NAME		LTTR	ENCL	ID CODE/NAME		LTTR	ENCL
PD5 LA		1	0	PD5 PD		5	5
HICKMAN, D		1	0				
INTERNAL: ACRS		10	10	AEOD/DOA		1	1
AEOD/DSP/TPAB		1	1	ARM TECH ADV		2	2
NRR/DLPQ/PEB		1	1	NRR/DOEA/EAB		1	1
NRR/DREP/RPB		1	1	NRR/PMAS/ILRB		1	1
REG FILE	01	1	1	RGN5		1	1
EXTERNAL: EG&G GROH, M		1	1	LPDR		1	1
NRC PDR		1	1	NSIC		1	1

**R  
I  
D  
S  
/  
A  
D  
D  
S**

TOTAL NUMBER OF COPIES REQUIRED: LTTR 31 ENCL 29



**Southern California Edison Company**

SAN ONOFRE NUCLEAR GENERATING STATION

P. O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

February 12, 1988

H. E. MORGAN  
STATION MANAGER

TELEPHONE  
(714) 368-6241

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Subject: Docket Nos. 50-361/50-362  
Monthly Operating Reports for January 1988  
San Onofre Nuclear Generating Station, Units 2 and 3

Enclosed are the Monthly Operating Reports as required by Section 6.9.1.10 of Appendix A, Technical Specifications to Facility Operating Licenses NPF-10 and NPF-15 for San Onofre Nuclear Generating Station, Units 2 and 3, respectively.

Also provided herein is a revised Unit 3 Operating Status Report for December 1987. The affected portions of the report have been annotated by an asterisk in the right hand margin. The revision was necessitated after a clerical error was discovered in the net generation for December 1987. The January 1988 Unit 3 report has already been adjusted for this error.

Please contact us if we can be of further assistance.

Sincerely,

Enclosures

cc: J. B. Martin (Regional Administrator, USNRC Region V)

F. R. Huey (USNRC Senior Resident Inspector, Units 1, 2 and 3)

Institute of Nuclear Power Operations (INPO)

8802230152 880212  
PDR ADOCK 05000361  
R DCD

TE2A  
11