

*Southern California Edison Company*



P. O. BOX 800  
2244 WALNUT GROVE AVENUE  
ROSEMEAD, CALIFORNIA 91770

September 15, 1982

Director, Office of Nuclear Reactor Regulation  
Attention: D. M. Crutchfield, Chief  
Operating Reactors Branch No. 5  
Division of Licensing  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Gentlemen:

Subject: Docket No. 50-206  
SEP Topic VI-7.B  
San Onofre Nuclear Generating Station  
Unit 1

By letter dated March 4, 1981 you requested information for your evaluation of SEP Topic VI-7.B, ESF Switchover From Injection to Recirculation Mode. This information was provided by our letter dated August 18, 1981 and was reflected in your evaluation for this topic dated September 4, 1981.

In our subsequent review of this correspondence we have discovered a typographical error in our August 18, 1981 letter which was also reflected in your topic evaluation. Specifically, the spring loaded check valve in the minimum flow lines which was identified as 256 should be 255. With this exception, your topic evaluation dated September 4, 1981 reflects the as-built facility.

If you have any questions on this matter, please let us know.

Very truly yours,

R. W. Krieger  
Supervising Engineer  
San Onofre Unit 1 Licensing

*A035*

8209170089 820915  
PDR ADOCK 05000206  
P PDR