## REGULATORY NEORMATION DISTRIBUTION S DEM (RIDS)

ACCESSION NBR:8212010171 DOC.DATE: 82/11/29 NOTARIZED: NO DOCKET # FACIL:50-361 San Onofre Nuclear Station, Unit 2, Southern Californ 05000361 50-362 San Onofre Nuclear Station, Unit 3, Southern Californ 05000362

AUTHOR AFFILIATION

DIETCH,R. Southern California Edison Co.

RECIP.NAME RECIPIENT AFFILIATION EISENHUT, D.G. Division of Licensing

SUBJECT: Responds to NRC 821026 ltr re Congressional request for info on steam generator tube integrity. Due to recent receipt of Obs, operating history does not provide meaningful info.

DISTRIBUTION CODE: BOOIS COPIES RECEIVED:LTR \_ ENCL \_ SIZE:\_\_\_\_\_
TITLE: Licensing Submittal: PSAR/FSAR Amdts & Related Correspondence

NOTES: J Hanchett 1cy PDR Documents, ELD Chandler 1cy.

05000361

NRR Scaletti 1cy.

J Hanchett 1cy PDR Documents. ELD Chandler 1cy.

05000362

NRR Scaletti 1cy.

	RECIPIENT	ECIPIENT COPIES		RECIPIENT		COPIES	
	ID CODE/NAME	LTTR E	NCL	ID CODE/NAM	E		ENCL
	NRR/DL/ADL	1	0	NRR LB3 BC		1	0
	NRR LB3 LA	1	0	ROOD,H.	01	1	1
INTERNAL:	ELD/HD\$2	. 1	0	IE FILE	• .	1	1
	IE/DEP EPDS 35	1	1	IE/DEP/EPLB	36	3	3
	NRR/DE/AEAB	1	0	NRR/DE/CEB	11	1	1
	NRR/DE/EQB 13	2	2	NRR/DE/GB	28	. 2	2
	NRR/DE/HGEB 30	1	1	NRR/DE/MEB	18	1	1
	NRR/DE/MTEB 17	1	1	NRR/DE/QAB	21	1	1
	NRR/DE/SAB 24	1	1 .	NRR/DE/SEB	25	1	1
	NRR/DHFS/HFEB40	1	1	NRR/DHFS/LQB	32	1	1
	NRR/DHFS/OLB 34	1	1	NRR/DL/SSPB		1	0
	NRR/DSI/AEB 26	1	1	NRR/DSI/CPB	10	1	1.1
	NRR/DSI/CSB 09	1	. 1	NRR/DSI/ICSB	16	1	1
	NRR/DSI/METB 12	ĩ	1	NRR/DSI/PSB	19	1	1
	NEW TOUTHAB 22	· i	1	NRR/DSI/RSB	23	1	1
	REG FILE 04	1	1	RGNS		. 3	- 3
`	RM/ODAMI/MIB	i	0				• •
EXTERNAL:	ACRS 41	6	6.	BNL (AMDTS ON	LY)	1	1
	DMB/DSS (AMDTS)	1	1	FEMA-REP DIV	39	1	1
	LPDR 03	. 1	1	NRC PDR	02	1	1
•	NSIC 05	1	1	NTIS		1	1
				,	1.5		
NOTES.	•	72	. 7	•,	162		

NOTES:

, 7

## Southern California Edison Company

SCE

P. O. BOX 800

2244 WALNUT GROVE AVENUE ROSEMEAD, CALIFORNIA 91770

November 29, 1982

TELEPHONE 213-572-4144

ROBERT DIETCH

Mr. Darrell G. Eisenhut, Director Division of Licensing Office of Nuclear Reactor Regulation U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Dear Mr. Eisenhut:

Subject: Congressional Request for Information Concerning

Steam Generator Tube Integrity (Generic Letter 82-22) San Onofre Nuclear Generating Station, Units 2 and 3

Docket Nos. 50-361 and 50-362

Your letter of October 26, 1982 to all Pressurized Water Reactor Licensees requests information regarding steam generator tube integrity. We understand this information is being requested in response to a request by Representative Edward J. Markey, Chairman of the Subcommittee on Oversight and Investigation.

In response to your above referenced letter, San Onofre Units 2 and 3 have only very recently received operating licenses with the full power license for Unit 2 received on September 7, 1982 and the low power license for Unit 3 received on November 15, 1982. Because of the recent receipt of these operating licenses we have not yet compiled an operating history to provide any meaningful response to your questions on steam generator tube integrity. Accordingly, we cannot provide a detailed response to the information request.

Very truly yours,

Cole & Autol

B001