RSB

DEC 16 1985

Docket Nos. 50-206, 50-361, 50-362

Southern California Edison Company P. O. Box 800 2244 Walnut Grove Avenue Rosemead, California 92770

Attention: Mr. Kenneth P. Baskin, Vice President

Nuclear Engineering Safety and Licensing

Gentlemen:

This refers to the routine inspection conducted by Messrs. F. R. Huey, J. P. Stewart, A. D'Angelo, J. E. Tatum, and Ms. R. C. Tang of this office during the period of September 27 through November 15, 1985 of activities authorized by NRC License Nos. DPR-13, NPF-10 and NPF-15 and to the discussion of our findings held by the inspectors with H. B. Ray and other members of the Southern California Edison staff at the conclusion of the inspection.

Areas examined during this inspection are described in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspectors.

No violations of NRC requirements were identified within the scope of this inspection.

Although not an apparent violation of NRC requirements, the inspection findings in paragraph 8.a of the enclosed report indicate a need for closer attention by management and Unit 1 staff personnel to the material condition of safety-related systems and components.

In accordance with $10\ \text{CFR}\ 2.790(a)$, a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this inspection, we will be glad to discuss them with you.

Sincerely, /5/

D. F. Kirsch, Deputy Director Division of Reactor Safety and Projects

Enclosure:

Inspection Report

Nos. 50-206/85-32, 50-361/85-31 and 50-362/85-30

cc w/enclosure:

D. J. Fogarty, Executive Vice President

H. B. Ray, Vice President (San Clemente)

H. E. Morgan, Station Manager (San Clemente)

State of California

bcc: RSB/Document Control Desk (RIDS)

Mr. J. Martin; Mr. B. Faulkenberry; G. Cook; Resident and Project Inspectors

> 8601080270 851216 PDR ADDCK 05000206 PDR

(E010)