



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION V

1450 MARIA LANE
WALNUT CREEK, CALIFORNIA 94596-5368

AUG 13 1992

Southern California Edison Company
Irvine Operations Center
23 Parker Street
Irvine, California 92718

Attention: Mr. Harold B. Ray
Senior Vice President, Nuclear

SUBJECT: RESOLUTION OF INSPECTION FINDINGS

REFERENCE: Letter from R. M. Rosenblum, SCE, to Mr. L. F. Miller, NRC,
dated August 3, 1992

The referenced letter provided your response to minor program implementation weaknesses. These weaknesses were identified by NRC inspectors during San Onofre Unit 1 Licensed Operator Simulator Requalification Training from June 10 through 12, 1992 and were documented in NRC Inspection Report No. 50-206-92-21.

We have reviewed your responses and corrective actions to the inspection findings and find them appropriate. Results of your corrective actions will be verified during future inspections.

Thank you for your cooperation.

Sincerely,


L. F. Miller, Jr., Chief
Reactor Safety Branch

For L. Miller, Jr

cc:
R. M. Rosenblum, SCE

9208250048 920813
PDR ADOCK 05000206
V PDR

*PWR 16
IEC1*

AUG 13 1992

bcc:
 J. B. Martin, RV
 K. E. Perkins, RV
 C. W. Caldwell, SRI
 J. O. Bradfute, Project Manager

REQUEST COPY	REQUEST COPY	REQUEST COPY
YES / NO	YES / NO	YES / NO

RUSSELL <i>CR</i>	MEADOWS <i>ME</i>	MILLER <i>ML</i>
8/13/92	8/13/92	8/13/92

COPY TO:	PDR	DCS
	YES/NO	YES/NO