## DISTRIBUTION DEMONSTRATION REGULATORY NFORMATION DISTRIBUTION STEM (RIDS)

ACCESSION NBR:8901040179 DOC.DATE: 88/12/29 NOTARIZED: NO DOCKET # FACIL: 50-206 San Onofre Nuclear Station, Unit 1, Southern Californ 05000206

AUTH.NAME AUTHOR AFFILIATION

MEDFORD, M.O. Southern California Edison Co.

RECIP.NAME RECIPIENT AFFILIATION

Document Control Branch (Document Control Desk)

SUBJECT: Advises that response to NRC 880531 questions re control

room habitability will be provided by 890417.

DISTRIBUTION CODE: A003D COPIES RECEIVED:LTR / ENCL TITLE: OR/Licensing Submittal: Suppl 1 to NUREG-0737(Generic Ltr 82-33)

NOTES: License Exp date in accordance with 10CFR2, 2.109.

05000206

R

5

	RECIPIENT ID CODE/NAME PD5 LA TRAMMELL,C	COPIES LTTR ENCL 1	RECIPIENT ID CODE/NAME PD5 PD	COPIES LTTR ENCL 7 1	
INTERNAL:	ARM/DAF/LFMB NUDOCS-ABSTRACT RES/DSIR/EIB	1 0 1 1 1	NRR/DLPQ/HFB 10 REG FILE 01	1 1 1 1	
EXTERNAL:	LPDR NSIC	1	NRC PDR	1	

## NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

J-VI

## Southern California Edison Company

P. O. BOX 800

2244 WALNUT GROVE AVENUE ROSEMEAD, CALIFORNIA 91770

M. O. MEDFORD

MANAGER OF

NUCLEAR REGULATORY AFFAIRS

December 29, 1988

TELEPHONE (818) 302-1749

U. S. Nuclear Regulatory Commission Attention: Document Control Desk Washington, D.C. 20555

Gentlemen:

Subject:

Docket No. 50-206

Control Room Habitability Review

NUREG-0737, Item III.D.3.4

San Onofre Nuclear Generating Station

Unit 1

By letter dated May 31, 1988, the NRC provided SCE with questions regarding the October 10, 1986 Control Room Habitability submittal. As indicated in SCE's letter dated September 9, 1988, the responses to the questions would not be available prior to November 1, 1988. The information has been prepared and SCE internal review and approval is necessary. It is expected that this will be completed and a response provided to the NRC by April 17, 1989. Delay in preparation, review and approval of the responses to the NRC questions is due to the efforts on transshipment, the Nuclear Instrumentation System upgrade and the Return To Service technical specifications in support of the Cycle 10 refueling.

If you have any questions or desire additional information please contact me.

Very truly yours,

monney

cc: J. B. Martin, Regional Administrator, NRC Region V

F. R. Huey, NRC Senior Resident Inspector, San Onofre Units 1, 2 and 3

8901040179 881229 PDR ADOCK 05000206 PNU

A003