Docket Nos. 50-206, 50-361 and 50-362

> Mr. Harold B. Ray Vice President Southern California Edison Co. Irvine Operations Center 23 Parker Street Irvine, California 92718

Mr. Gary D. Cotton Senior Vice President Engineering and Operations San Diego Gas & Electric Co. 101 Ash Street San Diego, California 92112

Gentlemen:

RESPONSE CONFIRMATION TO NRC BULLETIN 88-10 AND SUPPLEMENT 1 TO SUBJECT: BULLETIN 88-10 (TAC NOS. 71349, 71350 AND 71351)

By letters dated March 30, 1989 and September 6, 1989, Southern California Edison Company, et al., responded to Bulletin 88-10. As a result of Supplement 1 to Bulletin 88-10, corrections to your previous submittals were required and were forwarded by letters dated November 16, 1989 and March 12, 1990. Additionally, you stated that you would submit a report that summarizes the results of molded case circuit breaker tests. Your schedule for reporting is summarized as follows: Unit 1, Cycle 11 refueling outage; Unit 2, Cycle 5 refueling outage; and Unit 3. Cycle 5 refueling outage. By letter dated January 4, 1990, you supplied the Unit 2 report.

In your responses, you confirmed that activities required to address the issue of substandard molded case circuit breakers discussed in Bulletin 88-10 have been substantially performed, with the remaining actions to be performed on an acceptable schedule. A detailed technical review of the your responses has not been performed. However, the area may be subject to inspection at a later date. If a subsequent inspection identifies deficiencies in the your actions and responses, this issue will be reopened. Presently, the staff considers this action complete.

## Sincerely.

original signed by Lawrence E. Kokajko

Lawrence E. Kokajko, Project Manager Project Directorate V Division of Reactor Projects - III, IV, V and Special Projects Office of Nuclear Reactor Regulation

cc: See next page

DISTRIBUTION Docket File NRC & LPDRs PD5 Reading JZwolinski

CTramme11 **PShea** LKokajko

**EJordan** ACRS (10) PD5 Plant File

OGC

**JStone** 

DRSP/PD50  $PShea \rho \omega$ 3/20/90

[MCCB]

DRSP/PD5 MLKokajko:dr

PRSP/PD5 **ð**√atum

ANDRSP/D:PD5 ramme 11



## UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

March 21, 1990

Docket Nos. 50-206, 50-361 and 50-362

> Mr. Harold B. Ray Vice President Southern California Edison Co. Irvine Operations Center 23 Parker Street Irvine, California 92718

Mr. Gary D. Cotton
Senior Vice President
Engineering and Operations
San Diego Gas & Electric Co.
101 Ash Street
San Diego, California 92112

Gentlemen:

SUBJECT: RESPONSE CONFIRMATION TO NRC BULLETIN 88-10 AND SUPPLEMENT 1 TO

BULLETIN 88-10 (TAC NOS. 71349, 71350 AND 71351)

By letters dated March 30, 1989 and September 6, 1989, Southern California Edison Company, et al., responded to Bulletin 88-10. As a result of Supplement 1 to Bulletin 88-10, corrections to your previous submittals were required and were forwarded by letters dated November 16, 1989 and March 12, 1990. Additionally, you stated that you would submit a report that summarizes the results of molded case circuit breaker tests. Your schedule for reporting is summarized as follows: Unit 1, Cycle 11 refueling outage; Unit 2, Cycle 5 refueling outage; and Unit 3, Cycle 5 refueling outage. By letter dated January 4, 1990, you supplied the Unit 2 report.

In your responses, you confirmed that activities required to address the issue of substantially molded case circuit breakers discussed in Bulletin 88-10 have been substantially performed, with the remaining actions to be performed on an acceptable schedule. A datailed technical review of the your responses has not been performed. However, the area may be subject to inspection at a later date. If a subsequent inspection identifies deficiencies in the your actions and responses, this issue will be reopened. Presently, the staff considers this action complete.

Sincerely,

L. S. Kkyk

Lawrence E. Kokajko, Project Manager Project Directorate V

Division of Reactor Projects - III,

IV, V and Special Projects
Office of Nuclear Reactor Regulation

cc: See next page

Mr. Harold B. Ray Southern California Edison Company

cc: Charles R. Kocher, Esq. James A. Beoletto, Esq. Southern California Edison Company Irvine Operations Center 23 Parker Irvine, California 92718

Orrick, Herrington & Sutcliffe ATTN: David R. Pigott, Esq. 600 Montgomery Street San Francisco, California 94111

Alan R. Watts, Esq. Rourke & Woodruff 701 S. Parker St. No. 7000 Orange, California 92668-4702

Mr. Sherwin Harris
Resource Project Manager
Public Utilities Department
City of Riverside
3900 Main Street
Riverside, California 92522

Mr. Charles B. Brinkman Combustion Engineering, Inc. 12300 Twinbrook Parkway, Suite 330 Rockville, Maryland 20852

Mr. Phil Johnson U.S. Nuclear Regulatory Commission Region V 1450 Maria Lane, Suite 210 Walnut Creek, California 94596

Mr. Don Womeldorf Chief Environmental Management Branch California Department of Health 714 P Street, Room 616 Sacramento, California 95814 San Onofre Nuclear Generating Station, Units 2 and 3

Mr. Richard J. Kosiba, Project Manager Bechtel Power Corporation 12440 E. Imperial Highway Norwalk, California 90060

Mr. Robert G. Lacy Manager, Nuclear Department San Diego Gas & Electric Company P. O. Box 1831 San Diego, California 92112

Mr. John Hickman
Senior Health Physicist
Environmental Radioactive Mgmt. Unit
Environmental Management Branch
State Department of Health Services
714 P Street, Room 616
Sacramento, California 95814

Resident Inspector, San Onofre NPS c/o U.S. Nuclear Regulatory Commission Post Office Box 4329 San Clemente, California 92672

Mayor City of San Clemente San Clemente, California 92672

Regional Administrator, Region V U.S. Nuclear Regulatory Commission 1450 Maria Lane/Suite 210 Walnut Creek, California 94596

Chairman, Board of Supervisors San Diego County 1600 Pacific Highway, Room 335 San Diego, California 92101