

Comanche Peak Nuclear Power Plant, Units 3 & 4
COL Application
Part 2, FSAR




Figure 2.5.2-213 Contribution to 5 Hz Rock Total Mean Hazard