

## UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION II 245 PEACHTREE CENTER AVENUE NE, SUITE 1200 ATLANTA, GEORGIA 30303-1257

December 18, 2013

Gary J. Laughlin Chief Nuclear Officer and Head of Operations Louisiana Energy Services National Enrichment Facility, L.L.C. P.O. Box 1789 Eunice, NM 88231

SUBJECT: LOUISIANA ENERGY SERVICES, L.L.C., URENCO USA FACILITY, DOCKET

NUMBER 70-3103, AUTHORIZATION TO INTRODUCE URANIUM

**HEXAFLUORIDE INTO CASCADE 4.8** 

Dear Mr. Laughlin:

This letter confirms the U.S. Nuclear Regulatory Commission's (NRC's) authorization to introduce uranium hexafluoride into Cascade 4.8 at the Louisiana Energy Services (LES), URENCO USA Facility located in Eunice, New Mexico. This authorization is pursuant to the provisions of Title 10 of the *Code of Federal Regulations* (10 CFR) Part 70, Paragraph 70.32(k) and 10 CFR 40.41(g) that states, "No person may commence operation of a uranium enrichment facility until the Commission verifies through inspection that the facility has been constructed in accordance with the requirements of the license."

This NRC authorization is based on the results of construction and quality assurance inspections of various aspects of Assay 4 in Separation Building Module -1003, as described in the inspection reports listed in the Enclosure. The NRC staff determined that the systems, structures, and components designed to support safe operation of Cascade 4.8, including feed and withdrawal stations, were constructed in accordance with the requirements of your license. Specifically, our inspections provided: (1) reasonable assurance that the design, construction, and implementation of items relied on for safety (IROFS) will protect against natural phenomena and the consequences of potential accidents, (2) verification that the Quality Assurance Program was adequately implemented during construction, and (3) verification that the construction of the IROFS was completed in accordance with the documents comprising the license and the Integrated Safety Analysis.

The publically available inspection reports that describe the construction and quality assurance inspections of Cascade 4.8 are accessible through the NRC's Public Document Room, or from the Publicly Available Records System (PARS) component of NRC's Agencywide Documents Access and Management System (ADAMS) at <a href="http://www.nrc.gov/reading-rm/adams.htm">http://www.nrc.gov/reading-rm/adams.htm</a> using the accession numbers listed in the Enclosure.

Please note that this authorization does not apply to any Cascades other than Cascade 4.8, and it does not apply to processes or components associated with future phases of facility operations.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," this document may be accessed through ADAMS on the internet at <a href="https://www.nrc.gov/reading-rm/adams.htm">www.nrc.gov/reading-rm/adams.htm</a>.

Should you have any questions concerning this letter, please contact Mr. James Hickey at 404-997-4628.

Sincerely,

/RA/

Anthony T. Gody, Director Division of Fuel Facility Inspection

Docket No. 70-3103 License No. SNM-2010

Enclosure:

Construction and Quality Assurance Inspection Reports for Assay 4 in SBM-1003 as they Pertain to Cascade 4.8

cc: (See page 3)

Please note that this authorization does not apply to any Cascades other than Cascade 4.8, and it does not apply to processes or components associated with future phases of facility operations.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," this document may be accessed through ADAMS on the internet at www.nrc.gov/reading-rm/adams.htm.

Should you have any questions concerning this letter, please contact Mr. James Hickey at 404-997-4628.

> Sincerely, /RA/

Anthony T. Gody, Director Division of Fuel Facility Inspection

Docket No. 70-3103 License No. SNM-2010

Enclosure:

Construction and Quality Assurance Inspection Reports for Assay 4 in SBM-1003 as they Pertain to Cascade 4.8

cc: (See page 3)

## **DISTRIBUTION:**

B. Smith, NMSS

M. Raddatz. NMSS

M. Bailey, NMSS

M. Lesser, RII

- J. Yerokun, RII
- J. Munday, RII
- S. Freeman, RII
- J. Hickey, RII
- L. Pitts, RII
- S. Mendez, RII

**PUBLIC** 

X PUBLICLY AVAILABLE ☐ NON-PUBLICLY AVAILABLE ☐ SENSITIVE

X NON-SENSITIVE

ADAMS: X Yes ACCESSION NUMBER: ML13353A481 X SUNSI REVIEW COMPLETE X FORM 665 ATTACHED

OFFICE	RII:DFFI/BR2	RII:DFFI/BR2	RII:DFFI/BR2	RII:DFFI	
SIGNATURE	/RA/	RG for	/RA/		
NAME	S. Mendez	L. Pitts	J. Hickey	A. Gody	
DATE	12/16/2013	12/16/2013	12/16/2013		
E-MAIL COPY	YES NO	YES NO	YES NO	YES NO	

OFFICIAL RECORD COPY **AUTHORIZATION LETTER.DOCX** 

DOCUMENT NAME: G:\DFFI\BRANCH 2\LES\2013\CASCADE 4-8

## G. Laughlin

CC:

Butch Tongate, Deputy Secretary
New Mexico Department of Environment
Office of the Secretary
1190 St. Francis Drive
P. O. Box 26110
Santa Fe, NM 87502-0157

Matt White, Mayor City of Eunice P.O. Box 147/1106 Ave J Eunice, NM 88231

The Honorable Sam D. Cobb, Mayor City of Hobbs 200 E. Broadway Hobbs, NM 88240

Alton Dunn, Mayor City of Jal P.O. Drawer 340 Jal, NM 88252

Commissioner Gregory H. Fuller Chairman Lea County Board of County Commissioners Lea County Courthouse 100 North Main, Suite 4 Lovington, NM 88260

Daniel F. Stenger, Counsel Hogan and Hartson 555 13<sup>th</sup> Street, NW Washington, DC 20004 Michael Ortiz, Chief
Radiation Controls Bureau
Field Operations Division
Environmental Department
Harold S. Runnels Building
1190 St. Francis Drive, Room S 2100
P.O. Box 26100
Santa Fe, NM 87502-0157

Gregory Smith, President and Chief Executive Officer Louisiana Energy Services, L.L.C. Electronic Mail Distribution

Brenda Brooks, Director
Community Affairs and Government
Relations
Louisiana Energy Services, L.L.C.
Electronic Mail Distribution

Perry Robinson, Vice President Regulatory Affairs and General Counsel National Enrichment Facility P.O. Box 1789 Eunice, NM 88231

Richard A. Ratliff, PE, LMP
Radiation Program Officer
Bureau of Radiation Control
Department of State Health Services
Division for Regulatory Services
1100 West 49<sup>th</sup> Street
Austin, TX 78756-3189

## Construction and Quality Assurance Inspection Reports for Assay 4 in SBM-1003 as They Pertain to Cascade 4.8

Inspection Report Number	ADAMS Accession Number
2006-001	ML070190661
2007-001	ML071440430
2007-002	ML072280647
2007-003	ML073060571
2007-004	ML080670475
2008-001	ML081160345
2008-002	ML081930118
2008-003	ML083040618
2008-004	ML083540709
2008-006	ML090790642
2009-001	ML090850669
2009-002	ML091770643
2009-003	ML092730612
2009-004	ML093511013
2009-006	ML092820188
2010-005	ML100850424
2010-012	ML102020385
2011-002	ML111190268
2011-003	ML112070634
2011-004	ML11301A218
2012-002	ML12121A579
2012-004	ML12304A009
2012-005	ML13030A027
2013-002	ML13116A175
2013-003	ML13210A291
2013-004	ML13305A074
2013-005	Pending