

Ford Motor Company – RIC

2101 Village Rd., MD 1049

Dearborn, MI 48124

To whom it may concern,

This letter is to confirm that the above addressee returned five Aerosol Neutralizers that contained Krypton 85 to the manufacture of the devices. Confirmation of receipt and disposal from the receiving site was given on November 19, 2013. The receiving site was:

TSI, incorporated

500 Cardigan Rd,

Shoreview, Minnesota 55126

License #: 1153-103-62

The items returned are as follows:

Manufacturers name	<u>Model No</u> .	Serial No.
TSI Aerosol Neutralizer	3077	2431
TSI Aerosol Neutralizer	3077	2796
TSI Aerosol Neutralizer	3077	2459
TSI Aerosol Neutralizer	3077	2322
TSI Aerosol Neutralizer	3077	2689

Sincerely,

Scott Il:

Scott Larkins (Sr. Safety Engineer) December 9, 2013

Ford Motor Company,

197

Scientific Research Laboratory 2101 Village Rd., Rec. R. MD 1049 Dearborn, MI 48121-2053

Director, Office of Federal and State Materials and Environmental Management Programs Att: GLTS United States Nuclear Regulatory Commission Washington D.C. 20555-0001

أيرا أجاذا ودفار باز وارتابا وتار وبالأمر ويعار فالمان المراط بالرواري ويروزا

PRESSER PHINEY BOWLS

C P P FROM ZIP CODE 48126

7339

NON ()