



Rafael Flores
Senior Vice President &
Chief Nuclear Officer
rafael.flores@luminant.com

Luminant Power
P O Box 1002
6322 North FM 56
Glen Rose, TX 76043

T 254.897.5590
F 254.897.6652
C 817.559.0403

CP-201301460
Log # TXNB-13039

Ref. # 10 CFR 52

December 16, 2013

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555
ATTN: David B. Matthews, Director
Division of New Reactor Licensing

SUBJECT: COMANCHE PEAK NUCLEAR POWER PLANT, UNITS 3 AND 4
DOCKET NUMBERS 52-034 AND 52-035
SUPPLEMENTAL RESPONSE TO REQUEST FOR ADDITIONAL INFORMATION
169 (4846) (SECTION 10.2.3)

Dear Sir:

Luminant Generation Company LLC (Luminant) submits herein supplemental information for the response to Request for Additional Information 169 (4846) for the Combined License Application for Comanche Peak Nuclear Power Plant Units 3 and 4. The supplemental information addresses the turbine inspection program.

Should you have any questions regarding the attached supplemental information, please contact Don Woodlan (254-897-6887, Donald.Woodlan@luminant.com) or me.

There are no commitments in this letter.

I state under penalty of perjury that the foregoing is true and correct.

Executed on December 16, 2013.

Sincerely,

Luminant Generation Company LLC

A handwritten signature in black ink that reads "Donald R. Woodlan for".

Rafael Flores

Attachment: Supplemental Response to Request for Additional Information 169 (4846)

Electronic distribution:

Rafael.Flores@luminant.com
jeffry.simmons@luminant.com
Stephanie.Moore@energyfutureholdings.com
Ken.Peters@luminant.com
Robert.Bird@luminant.com
Allan.Koenig@luminant.com
Eric.Evans@luminant.com
Robert.Reible@luminant.com
donald.woodlan@luminant.com
John.Conly@luminant.com
Janice.Caldwell@luminant.com
David.Beshear@txu.com
Fred.Madden@luminant.com
Debra.Gilliam@luminant.com
Brad.Watson@luminant.com
Mark.Clark@luminant.com
Thomas.Mccool@luminant.com
NuBuild Licensing files
sfrantz@morganlewis.com
tmatthews@morganlewis.com
tomo_imamura@mhi.co.jp
masahiko_morino@mhi.co.jp
kano_saito@mhi.co.jp
shigemitsu_suzuki@mhi.co.jp
yoshiki_ogata@mnes-us.com
Luminant Records Management (.pdf files only)
Marc.Dapas@nrc.gov
masanori_onozuka@mnes-us.com
greg_rolfson@mnes-us.com
joseph_tapia@mnes-us.com
michael_melton@mnes-us.com
michael_tschiltz@mnes-us.com
atsushi_kumaki@mnes-us.com
yukako_hill@mnes-us.com
sean_ton@mnes-us.com
ryan_sprengel@mnes-us.com
molly_spalding@mnes-us.com
mory_diane@mnes-us.com
rjb@nei.org
kra@nei.org
michael.takacs@nrc.gov
cp34update@certrec.com
David.Matthews@nrc.gov
Balwant.Singal@nrc.gov
Stephen.Monarque@nrc.gov
perry.buckberg@nrc.gov
john.kramer@nrc.gov
Rayo.Kumana@nrc.gov
Frank.Akstulewicz@nrc.gov
ComanchePeakCOL.Resource@nrc.gov
Sujata.Goetz@nrc.gov
Art.Howell@nrc.gov
Samuel.Lee@nrc.gov
Jennifer.Dixon-Herrity@nrc.gov

SUPPLEMENTAL RESPONSE TO REQUEST FOR ADDITIONAL INFORMATION

Comanche Peak, Units 3 and 4

Luminant Generation Company LLC

Docket Nos. 52-034 and 52-035

RAI NO.: 169 (4846)

SRP SECTION: 10.02.03 - Turbine Rotor Integrity

**QUESTIONS for Component Integrity, Performance, and Testing Branch 1 (AP1000/EPR Projects)
(CIB1)**

DATE OF RAI ISSUE: 7/8/2010

QUESTION NO.: 10.02.03-02

Revision 1 of the Comanche Peak COL FSAR revised Section 10.2.3.5 to state that a turbine maintenance and inservice inspection procedure will be established prior to fuel load. However, the description of the inspection program, including the inspection intervals were not provided in this revised COL FSAR Section 10.2.3.5, as requested in the NRC staff's RAI Number 6 (2614). Therefore, Luminant is requested to provide the following information in order to meet the requirements of General Design Criterion 4 of 10 CFR Part 50:

- a) The guidelines in Section C.I.10.2.3.5 of Part I to Regulatory Guide (RG) 1.206 specify that if the plant-specific inspection program is not available at the time of the COL application, the representative information (description of the inspection program and inspection interval) may be submitted for staff review as part of the COL application. Therefore, describe the inservice inspection program and inspection intervals in the COL FSAR, or specify in the COL FSAR that the inspection procedure will be consistent with the inspection program and inspection intervals identified in Section 10.2.3.5 of the US-APWR DCD FSAR.
- b) The submittal and implementation of the inservice inspection procedure should be included as a proposed license condition in Section 3 to Part 10 of the Comanche Peak COL application since this item will not be resolved prior to the issuance of the license. The proposal of a license condition, as discussed in Section C.I.10.2.3.5 of Part I to RG 1.206, ensures that the as-built plant is consistent with the design reviewed during the licensing process.

SUPPLEMENTAL INFORMATION S01:

This supplemental information is provided for the original response submitted on August 9, 2010 (ML102230154). The original response added a Turbine Inspection Program as a license condition in Subsection 3 of Part 10 of the COLA. In a later COLA revision, the individual license conditions for operational programs were combined into a single license condition that included the programs specifically designated in FSAR Table 13.4-201. The original response is not changed, but the Turbine

Inspection Program has been added to Table 13.4-201 as an operational program with a license condition as the implementing requirement.

Impact on R-COLA

See attached marked-up FSAR Revision 4 page 13.4-12.

Impact on DCD

None.

**Comanche Peak Nuclear Power Plant, Units 3 & 4
COL Application
Part 2, FSAR**

CP COL 13.4(1)

Table 13.4-201 (Sheet 11 of 11)

Operational Programs Required by NRC Regulation and Program Implementation

Item	Program Title	Program Source (Required By)	FSAR (SRP) Section	Implementation	
				Milestone	Requirement
22.	Special Nuclear Material Control and Accounting Program	10 CFR 74 Subpart B (§§ 74.11 - 74.19, excluding 74.17)	13.5.2.2	Prior to receipt of special nuclear material	License Condition
<u>23</u>	<u>Turbine Inspection Program</u>	<u>10CFR50 Appendix A (GDC-4)</u>	<u>3.5.1.3.2</u> <u>10.2.3.5</u>	<u>Prior to initial fuel load</u>	<u>License condition</u>

RCOL2_10.0
2.03-2 S01

(1) Inservice Testing Program will be fully implemented by generator on line on nuclear heat. Appropriate portions of the program are implemented as necessary to support the system operability requirements of the Technical Specifications.