

**Open Generic Communication TACs (PA No. 115126CA/B)
Summary Report (AS OF 12/31/2013)**

TAC NO.	TAC TITLE	AGE (Mon)	TAC OPENED	LEAD ORG
ME5167	RIS 'Staff Position on the Clarification of Submitting of Alter. Under 10 CFR 50.55'	37.0	12/13/2010	DE
ME9020	RIS 'Embedded Digital Devices in Safety Systems'	18.0	07/09/2012	NRO
MF0541	RIS 'NRC Position on SSCs Requiring Protection from Tornado Missiles'	12.0	01/23/2013	DSS
MF1404	RIS 'Withdrawal of NRC Generic Letter 95-08 and Endorsement of NEI 11-08'	9.0	04/10/2013	NSIR
MF1773	RIS 'License Renewal Guidance for Part 50 versus Part 54 Issues'	8.0	05/13/2013	DLR
MF2273	RIS 'Enhancements To The Vendor Inspection Program'	7.0	06/18/2013	NRO
MF2561	RIS 'Maintaining the Effectiveness of License Renewal Aging Management Programs'	5.0	08/13/2013	DLR
MF2932	RIS 'Clarification of Fracture Toughness Requirements for Ferritic RCPB Components'	3.0	10/22/2013	DE
MF3180	RIS 'Designation Guide for Safeguards Information (DG-SGI-1) to Nonpower Reactors'	1.0	12/05/2013	PROB
MF3181	RIS 'Administration of 10 CFR Part 72 Certificates of Compliance and Amendments'	1.0	12/05/2013	NMSS
MF3182	RIS 'Seismic Analysis Methods for Spent Fuel Dry Cask Loading Stack-up Configuration'	1.0	12/05/2013	NMSS
MF3186	RIS 'Regulatory Reqts for Withholding Proprietary Info from Public Disclosure'	1.0	12/05/2013	LB
MF0921	IN 'Quasi-Laminar Indications in Reactor Pressure Vessel Forgings'	10.0	03/08/2013	DE

**Open Generic Communication TACs (PA No. 115126CA/B)
Summary Report (AS OF 12/31/2013)**

TAC NO.	TAC TITLE	AGE (Mon)	TAC OPENED	LEAD ORG
MF1357	IN 'Refueling Water Storage Tanks'	9.0	04/03/2013	PGCB
MF1794	IN 'Flange Leakoff Line Inspection'	8.0	05/16/2013	DE
MF1921	IN 'Teflon Material Degradation Affecting Containment Integrity and Class 1E EQ Functions'	8.0	05/31/2013	DORL
MF2313	IN 'Steam Generator Channel Head and Tubesheet Degradation'	7.0	06/25/2013	DE
MF3105	IN 'Fuel Safety Limit Calculation Inputs Were Inconsistent with NRC-Approved Fuel Design'	2.0	11/20/2013	DSS
MF3142	IN 'TDAFW Pump Overspeed Trip Mechanism Issues'	2.0	11/26/2013	DIRS
MF2553	IN 'Degraded Voltage Protection Relay Malfunction Due To Harmonics In Power Systems'	5.0	08/08/2013	DE
ME9843	GL 'Treatment of Natural Phenomena Hazards At Fuel Cycle Facilities'	15.0	10/25/2012	NMSS
MF0581	GL 'Degradation of Neutron Absorbing Material in Spent Fuel Pools'	12.0	01/29/2013	DSS