


Mid-America Calibrations
License No. 24-32531-01
Control No. 582213

Mr. Karl E. Artinger:

I have reviewed your application for license renewal dated September 24, 2013, and require additional information before I can complete my review of your renewal. Please address the following in writing:

1. Confirm that the radioactive material to be listed on your renewed license is the same as the material listed on your current license in Subitems 6., 7. and 8. This was item was addressed in your application.
2. Please provide a description of the training and experience for proposed authorized users and the training to be provided to ancillary personnel. You may reference the model training program in Appendix H of NUREG-1556, Vol. 18, "Program Specific Guidance about Service Provider Licensee" or provide a comparable training program.
3. Please provide the leak test procedure used for your clients or state that your will follow the model procedure in Appendix O of NUREG-1556, Vol. 18, "Program Specific Guidance about Service Provider Licensee".
4. Do you provide your clients with a leak test kit? If so, what does that kit contain?
5. Please provide the procedure used for calibrating radiation detection instruments for your clients. You may reference the model calibration procedure in Appendix J of NUREG-1556, Vol. 18, "Program Specific Guidance about Service Provider Licensee" or provide comparable calibration procedures.
6. On page 1 of your application you state that you do not ship or **store** licensed materials. Where is the Cs-137 instrument calibrator stored if not stored at 808 S. W. Nautica Court?
7. Page 3 of your application states that Mid-America Calibrations, Inc. produces no radioactive waste. If that is so, where are contaminated leak test samples kept or sent (greater than 0.005 microcuries/sample)?

Please respond to each of the items above in writing on letterhead signed by the RSO or a member of management. You may email your response to me or fax your response to 630-515-1078. Please provide your response no later than January 31, 2014. If you have any questions, please call me at 630-829-9842.


Toye L. Simmons

1/15/14
Date

Simmons, Toye

From: Simmons, Toye
Sent: Wednesday, January 15, 2014 9:03 AM
To: 'midamcal@att.net'
Subject: Request for informatiion
Attachments: Scan001.PDF

Mr. Artinger, I have been assigned your license renewal and I have a few questions and need additional information which is attached. Please feel free to contact me if you have questions.

Toye L. Simmons
Materials Licensing Branch
U.S. Nuclear Regulatory Commission
Region III
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4352
Office: (630) 829-9842
Fax: (630) 515-1078