NRC FORM 591M PART 1 (07-2012)* 10 CFR 2.201	PECTION REPORT		U.S. NUCLEAR REGULATORY COMMISSION D COMPLIANCE INSPECTION		
1. LICENSEE/LOCATION INSPECTED: Boehringer Ingelheim Pharmaceuticals, Inc. 900 Ridgebury Road Ridgefield, Connecticut 06877-0368 REPORT NUMBER(S) 2014-001			2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713		
3. DOCKET NUMBER(S)		4. LICENSE NUMBER(S)		5. DATE(S) OF INSPECTION	
030-17101		06-19183-01		1/9-10/2014	
LICENSEE:					
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X					
Statement of Corrective Actions I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.					
Title		Printed Name		Signature	Date
LICENSEE'S REPRESENTATIVE	Bill	Galdenz	Wille	un Held	1/14/14
NRC INSPECTOR	John Mil	ler	John 1	Miller	1/14/2014
BRANCH CHIEF	Blake W	elling	I Shah U		1/22/14
*NRC FORM 591M PART 1 (07-2012) (RI Rev. 0	9/12/2013) G:\WordDo	cs\Current\insp Record\R06-	19183-01.2014001.591MF	Part1.doc
SUNSI Review Completed By:	/RA/	JMiller		X Public X	Non-Sensitive