NRC FORM 591M PART 1 (07-2012)* 10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION				
1. LICENSEE/LOCATION INSPECTED: ATC Group Services, Inc. dba Cardno ATC 3 Terrie Lane, Suite 4 Burlington, New Jersey 08016 REPORT NUMBER(S) 2014-001		NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713		
3. DOCKET NUMBER(S) 030-36466	4. LICENSE NUMBER(\$ 29-30863-01	(S)	5. DATE(S) OF INSPECTI 2/21/14	ON
LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X				
Statement of Corrective Actions I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken,				
'	,	vritten response	to NRC will be required, unless specifical	
Title LICENSEE'S REPRESENTATIVE	Printed Name		Signature	Date
NRC INSPECTOR	Michael Reichard		/RA/	2/21/14
BRANCH CHIEF	Blake Welling		/RA EUllrich f/	2/24/14
*NRC FORM 591M PART 1 (07-2012) (RI Rev. 09/12/2013)	G:\WordDocs\C	urrent\Insp Record\R29-30863-01.201400	1.591M-Part1.doc
SUNSI Review Completed By:	/ RA / Michael Reichar	rd	x Public x	Non-Sensitive