

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION II 245 PEACHTREE CENTER AVENUE NE, SUITE 1200 ATLANTA, GEORGIA 30303-1257

March 10, 2014

Mr. Dominique Grandemange Site Manager, Richland Facility AREVA NP, INC. 2101 Horn Rapids Road Richland, Washington 99352

SUBJECT: AREVA NP – RICHLAND, LICENSEE PERFORMANCE REVIEW (NUCLEAR REGULATORY COMMISSION INSPECTION REPORT 70-1257/2014-001)

Dear Mr. Grandemange:

The Nuclear Regulatory Commission (NRC) Region II and Headquarters staff completed a review of the AREVA NP fabrication facility performance in conducting NRC licensed activities. The review covered the period of January 1, 2012, through December 31, 2013. The performance of AREVA NP was evaluated in the following areas: Safety Operations, Radiological Controls, Facility Support, and Other Areas. The enclosure to this letter provides the results of our review and will be used as a basis for establishing the NRC oversight program for your facility. The details regarding the Safeguards portion of the review are documented in a separate letter marked "Official Use Only" due to the sensitive nature of that information.

Overall, the staff determined that AREVA NP has continued to conduct activities safely and securely, while protecting public health and the environment. Based on our review of activities, no area needing improvement was identified. Therefore, the NRC will conduct the core inspection program for a Category III Fuel Facility as described in NRC Inspection Manual Chapter 2600, "Fuel Cycle Facility Operational Safety and Safeguards Inspection Program," for the period of January 1 through December 31, 2015.

The staff is continuing its efforts to assess Unresolved Item 2012-006-01 and compliance with the requirements of Title 10 of the *Code of Federal Regulations* (10 CFR) Part 70 regarding accident sequences and potential consequences associated with natural phenomena events.

The results of our review will be discussed with you at a meeting open to the public on April 9, 2014. During the meeting, we expect you to discuss your performance in the same major areas as evaluated by the NRC.

In accordance with 10 CFR Part 2.390 of NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room, or from the NRC's Agencywide Documents Access and Management System (ADAMS), which is accessible from the NRC Website at http://www.nrc.gov/reading-rm/adams.html.

D. Grandemange

2

Please refer questions and comments regarding NRC's review of your performance to Mr. Marvin Sykes, Chief, Projects Branch 2, by telephone at 404-997-4629.

Sincerely,

/RA/

Anthony T. Gody, Director Division of Fuel Facility Inspection

Docket No. 70-1257 License No. SNM-1227

Enclosure: Licensee Performance Review

cc: (See page 3)

D. Grandemange

Please refer questions and comments regarding NRC's review of your performance to Mr. Marvin Sykes, Chief, Projects Branch 2, by telephone at 404-997-4629.

Sincerely,

/**RA**/

Anthony T. Gody, Director Division of Fuel Facility Inspection

Docket No. 70-1257 License No. SNM-1227

Enclosure: Licensee Performance Review

cc: (See page 3)

DISTRIBUTION: A. Gody, RII M. Sykes, RII M. Thomas, RII M. Bailey, NMSS M. Baker, NMSS M. Diaz, NMSS M. Franovich, NMSS C. Haney, NMSS P. Habighorst, NMSS R. Johnson, NMSS S. Moore, NMSS PUBLIC

X PUBLICLY AVAILABLE

□ NON-PUBLICLY AVAILABLE

□ SENSITIVE X NON-SENSITIVE

ADAMS: X Yes ACCESSION NUMBER: ML14070A319 X SUNSI REVIEW COMPLETE X FORM 665 ATTACHED

OFFICE	RII:DFFI	RII:DFFI	NMSS				
SIGNATURE	/RA/	/RA/	J. Andersen for				
NAME	MCrespo	MSykes	MBailey				
DATE	03/ 6 /2014	03/6 /2014	03/ 6 /2014	3/ /2014	3/ /2014	3/ /2014	3/ /2014
E-MAIL COPY?	YES NO	YES NO	YES NO	YES NO	YES NO	YES NO	YES NO

OFFICIAL RECORD COPY DOCUMENT NAME: G:\DFFI\ASSESS LPR\AREVA NP RICHLD\2014 LPR\AREVA NON-SAFEGUARDS LPR LETTER-2014-REV 2.DOCX cc: Loren J. Maas, Manager Licensing and Compliance Areva NP, Inc. 2101 Horn Rapids Road Richland, Washington 99352

Thomas Scott Wilkerson Vice President, Engineering Areva NP, Inc. 3315 Old Forest Road Lynchburg, Virginia 24501

Ronald J. Land, Senior Vice President US Fuel Business Unit Areva NP Mt. Athos Road Site 1724 Mount Athos Road P.O. Box 11646 Lynchburg, VA 24506-1646

Robert E. Link, Manager Environmental, Health, Safety & Licensing Areva NP 2101 Horn Rapids Road Richland, Washington 99352

Calvin D. Manning, Manager Nuclear Criticality Safety Areva NP 2101 Horn Rapids Road Richland, Washington 99352

Clark Halverson, Director Division of Radiation Protection Department of Health, Bldg 5 PO Box 47827 7171 Cleanwater Lane Olympia, Washington 98504-7827

Earl Fordham Eastern Regional Director Office of Radiation Protection Department of Health 309 Bradley Boulevard, Suite 201 Richland, Washington 99352

LICENSEE PERFORMANCE REVIEW FOR AREVA-RICHLAND

ASSESSMENT PERIOD: JANUARY 1, 2012 TO DECEMBER 31, 2013

The following is a summary of the performance of Areva-Richland in the conduct of NRC-licensed activities.

PERFORMANCE AREA: SAFETY OPERATIONS

This area is comprised of plant operations, nuclear criticality safety, and fire protection.

Program Areas Needing Improvement

• No specific area needing improvement was identified in Safety Operations.

Recommended NRC Inspection Effort

• Maintain the core inspection effort in Safety Operations.

PERFORMANCE AREA: RADIOLOGICAL CONTROLS

This area is comprised of radiation protection, environmental protection, waste management, and transportation.

Program Areas Needing Improvement

• No specific area needing improvement was identified in Radiological Controls.

Recommended NRC Inspection Effort

• Maintain the core inspection effort in Radiological Controls.

PERFORMANCE AREA: FACILITY SUPPORT

This area is comprised of maintenance and surveillance, training, emergency preparedness, management organization and controls, and permanent plant modifications.

Program Areas Needing Improvement

• No specific area needing improvement was identified in Facility Support.

Recommended NRC Inspection Effort

• Maintain the core inspection effort in Facility Support.

PERFORMANCE AREA: OTHER AREAS

This area is comprised of special issues.

Program Areas Needing Improvement

• No specific area needing improvement was identified in Other Areas.

Recommended NRC Inspection Effort

• Maintain the core inspection effort in Other Areas.