NRC FORM 591M PART 1 (07-2012)* 10 CFR 2.201	ETY INSPECTION REPORT	AND COMF	U.S. NUCLEAR REGULATO PLIANCE INSPECTION	RY COMMISSION
1. LICENSEE/LOCATION INSPECTED: Cabell Huntington Hospital 1340 Hal Greer Boulevard Huntington, West Virginia 25701-0195		2. NRC/REGIONAL OFFICE  U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713		
REPORT NUMBER(S)  3. DOCKET NUMBER(S)	2014001 4. LICENSE NUMBER(	<u> </u> (S)	5. DATE(S) OF INSPECT	ION
030-03370		00404-02	February 25-26, 2014	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:    X				
corrective actions is made in accorda	nce with the requirements of 10 CFR	R 2.201 (correcti	ken to correct the violations identified. The ve steps already taken, corrective steps we to NRC will be required, unless specifical	vhich will be taken,
Title	Printed Name		Signature	Date
LICENSEE'S REPRESENTATIVE				
NRC INSPECTOR	Robin Elliott		/RA/	3/7/14
BRANCH CHIEF	James Dwyer		/RA/	3/19/14
*NRC FORM 591M PART 1 (07-2012	) (RI Rev. 09/12/2013)	G:\WordDocs\C	urrent\Insp Record\R47-00404-02.201400	)1.591M-Part1.doc
SUNSI Review Completed By:	/RA/ RElliott		x Public x	Non-Sensitive