



PSEG Power, LLC

PSEG Site ESPA
Part 2, Site Safety Analysis Report

Smooth Mean Rock 10⁻⁴, 10⁻⁵,
and 10⁻⁶ Annual Frequency of
Exceedance UHRS

FIGURE 2.5.2-76

Rev 0