

U.S. Nuclear Regulatory Commission Attn: Audrey L. Klett Project Manager Turkey Point Plant One White Flint North 11555 Rockville Pike Rockville, MD 20852-2746

Re: Turkey Point Units 3 and 4 Docket Nos. 50-250 and 50-251

Revised References for Response to NRC Request for Information Pursuant to 10 CFR 50.54(f) Regarding the Flooding Aspects of Recommendation 2.1 of the Near-Term Task Force Review of Insights from the Fukushima Dai-ichi Accident

## References:

- 1. FPL Letter, M. Kiley to NRC, L-2014-023, Florida Power and Light Company's, Turkey Point Units 3 and 4, Response To NRC Request For Additional Information Regarding Flood Hazard Reevaluation Report (FHRR), Recommendation 2.1 –Flooding, Dated January 31, 2014, ADAMS Accession No. ML ML14055A365
- 2. FPL Letter, M. Kiley to NRC, L-2014-043, Florida Power and Light Company's, Turkey Point Units 3 and 4, Response To Request For Additional Information (RAI) 6, 10, and 11 Regarding Supplemental Response to NRC Request for Information Pursuant to 10 CFR 50.54(f) Regarding the Flooding Aspects of Recommendation 2.1 of the Near-Term Task Force Review of Insights from the Fukushima Dai-ichi Accident, dated February 26, 2014, ADAMS Accession No. ML14073A065
- 3. FPL Letter, M. Kiley to NRC, L-2013-087, Response to NRC Request for Information Pursuant to 10 CFR 50.54(f) Regarding the Flood Hazard Reevaluation of Recommendation 2.1, dated March 11, 2013, ADAMS Accession No. ML13095A196
- 4. FPL Letter, M. Kiley to NRC, L-2014-046, Florida Power and Light Company's, Turkey Point Units 3 and 4, References for Response to NRC Request for Information Pursuant to 10 CFR 50.54(f) Regarding the Flooding Aspects of Recommendation 2.1 of the Near-Term Task Force Review of Insights from the Fukushima Dai-ichi Accident, dated February 26, 2014, ADAMS Accession No. ML14077A174
- 5. FPL Letter, M. Kiley to NRC, L-2014-116, Florida Power and Light Company's, Turkey Point Units 3 and 4, Revised Response To Request For Additional Information Question

Florida Power & Light Company 9760 S.W. 344<sup>th</sup> Street Homestead, FL 33035

ADIO

Six Regarding Supplemental Response to NRC Request for Information Pursuant to 10 CFR 50.54(f) Regarding the Flooding Aspects of Recommendation 2.1 of the Near-Term Task Force Review of Insights from the Fukushima Dai-ichi Accident, dated April 25, 2014.

References 1 and 2 submitted FPL's responses to NRC RAI questions on the Turkey Point Flooding Harzards Re-evaluation Report submitted in Reference 3. Reference 4 submitted supporting documentation and references used in FPL's response to the RAIs. Reference 5 submitted a revised response to RAI question 6 due to changes in the calculation used for determining maximum flood levels.

The purpose of this letter is to provide the revised computer files from the FLO-2D model previously submitted in Reference 4 that were used in developing the revised RAI question 6 response. The CDs with the FLO-2D computer files are enclosed.

This letter does not include any additional and or new regulatory commitments.

Should you have any questions concerning the content of this letter, please contact Mr. Robert J. Tomonto, Turkey Point Licensing Manager, at 305-246-7327.

Sincerely,

Michael Kiley

Enclosure

cc: USNRC Regional Administrator, Region II, w/o enclosures

USNRC Document Desk, Turkey Point Nuclear Plant, w/o enclosures

USNRC Senior Resident Inspector, Turkey Point Nuclear Plant, w/o enclosures

Florida Power & Turkey Point Lic 9760 SW 344<sup>th</sup> : Homestead, FL. 33035

DOCUMENT CONTROL DESK U.S. Nuclear Regulatory Commission Washington, D. C. 20555-0001