NRC FORM 591M PART 1			U.S. NUCLEAR REGULATORY COMMISSION	
(4-2008) 10 CFR 2.201	CAFETYING	PECTION REPORT AND	COMPLIANCE II	AISDECTION
	SAFEITINS	PECTION REPORT AND	COMPLIANCE	NSPECTION
1. LICENSEE/LOCATION INSPECTED:			2. NRC/REGIONAL OFFICE	
Epson America, Inc. 3840 Kilroy Airport Way Long Beach, California 90806-2452 Location: 3840 Kilroy Airport Way, Long Beach, CA and 18300 Central Avenue, Carson, CA			U.S. Nuclear Regulatory Commission - Region IV 1600 East Lamar Boulevard Arlington, Texas 76011-4511	
	37800/2014-001			C
3. DOCKET NUMBER 030-37800		4. LICENSE NUMBER 04-23970-01E		5. DATES OF INSPECTION May 05-12, 2014
LICENSEE:		04-23970-01L		Iviay 05-12, 2014
The inspection was an e Regulatory Commission procedures and represent X 1. Based on the X 2. Previous vio 3. The violation identified, no discretion, we Non-Cited V 4. During this in	(NRC) rules and regular ntative records, interview e inspection findings, no lation closed. as(s), specifically describ n-repetitive, and correct ere satisfied. fiolation(s) was/were dis	tions and the conditions of your vs with personnel, and observation violations were identified. Deed to you by the inspector as notive action was or is being taken, increased involving the following respectives.	incense. The inspection ions by the inspector. on-cited violations, are and the remaining critequirement(s) and Correspond to the corresponding to the corre	n violation of NRC requirements and are being
corrective actions is made	30 days, the actions de e in accordance with the e will be achieved). I und Printed Nan R. Rick Muño	e requirements of 10 CFR 2.201 derstand that no further written r ne	will be taken to correct (corrective steps alrea esponse to NRC will be Signature	the violations identified. This statement of ady taken, corrective steps which will be taken, e required, unless specifically requested. Date 05/12/2014 6/2/2014 BRANCH FORMS\591M FORMS\Part1 Publicly Available.doc
Non-Public	Sensitive - Sec	urity-Related		Public X Non-Sensitive