

## Roldan, Lizette

---

**From:** Roldan, Lizette  
**Sent:** Thursday, May 08, 2014 11:18 AM  
**To:** 'cdixon@acuren.com'  
**Subject:** REQUEST FOR ADDITIONAL INFORMATION REGARDING AMENDMENT CONTROL 583773  
**Attachments:** Appendix F.pdf

**Importance:** High

License No.: 50-32443-01  
Docket No.: 030-38596  
Control No. 583773

**PUBLIC**

- Immediate Release  
 Normal Release

**NON-PUBLIC**

- A.3 Sensitive-Security Related  
 A.7 Sensitive Internal  
 Other: \_\_\_\_\_

Reviewer: JMO Date: 6/16/14

Dear Mr. Dixon:

This is in reference to your letter dated April 3, 2014 requesting to amend Nuclear Regulatory Commission License Number 50-32443-01. In order to continue our review, we need the following additional information:

1. Based on the organizational chart we have on file for Acuren USA, the submission for an amendment request must come from the RSO or manager from the Acuren USA office, or the Acuren Corporate Director for Radiation Safety. If you hold one of these positions, provide a statement: "I am currently the **state position** and am authorized to make legally binding commitments on behalf of Acuren USA with matters pertaining to and with the US Nuclear Regulatory Commission." Another option is to have the Acuren USA Regional Manager write a letter confirming you are authorized to make legally binding commitments on behalf of Acuren USA with matters pertaining to and with the US Nuclear Regulatory Commission.
2. Provide a license number (if issued by NRC) or a copy of the license (if issued by an Agreement State) on which you are specifically named as Radiation Safety Officer for the uses requested, **OR** Provide proof that you are qualified to be the RSO in accordance with 10 CFR 34.42. I have attached a link to 10 CFR 34.42 for your convenience. <http://www.nrc.gov/reading-rm/doc-collections/cfr/part034/part034-0042.html>
3. Considering the distance between your current location and the location of use for Acuren USA, please address the following:
  - a. Description of how you will allocate time to permit the performance of the duties of an RSO as described in the regulations. State the minimum amount of on-site time (hours per week or month).
  - b. Appoint an in-house representative who will serve as the point of contact during the your absence. This person may be allowed to assist you with limited authority.
  - c. Describe the overall availability to respond to questions or operational issues that arise during the conduct of the radiation safety program and related regulatory requirements.
  - d. Specify the maximum amount of time it will take you to arrive at the facility in the event of an emergency that requires your presence.
4. You are requesting to change the mailing address on the license. In the request the name of the company states Acuren Inspection, Inc and not Acuren USA. If you are requesting to have the name of

the company changed, complete and submit the attached form titled "Appendix F", and explain whether a change of ownership will occur or you are requesting only a name change. Please note, change of ownerships must be posted on the NRC website for 30 days. If your intent was to receive all future amendments, we can send a copy of future amendments to the address listed on the letter, in addition to the mailing address currently on the license.

5. To obtain a better understanding on the organizational structure of Acuren, provide an organizational chart breakdown showing the correct corporate lineage starting with the parent company down. Include current managerial positions with titles and the name of the individual currently holding the position with regards to the nondestructive testing operations associated to the NRC license.

We will continue our review upon receipt of this information. You may respond by email attachment in PDF format. In your response, refer to Mail Control No. 583773. If you have any technical questions regarding this deficiency letter, please call me at (817) 200-1596. Please respond to this request by June 9, 2014.

Thanks,

Lizette Roldán-Otero, Ph.D.  
US NRC Region IV – NMSB-B  
1600 Lamar Blvd  
Arlington, TX 76011  
Office: 817-200-1596  
Fax: 817-200-1188