SAFEGUARDS II LEAR REGULA, NUCLEAR REGULATORY COMMISSION **REGION II** 101 MARIETTA STREET, N.W. ŝ ATLANTA, GEORGIA 30323 SEP 1 2 1986 Report No.: 50-261/86-24 Licensee: Carolina Power and Light Company P. O. Box 1551 Raleigh, NC 27602 Docket No.: 50-261 License No.: DPR-23 Facility Name: H. B. Robinson Inspection Conducted: August 18 and 19, 1986 Inspector cal Security Inspector

ianed

SUMMARY

Scope: This special announced reactive inspection was conducted onsite inspecting the area of Physical Protection of Safeguards Information.

McGuire, Chief, Physical Security Section

Nuclear Materials Safety and Safeguards Branch Division of Radiation Safety and Safeguards

Results: The licensee was found to be in violation of NRC requirements within the area inspected.

Failure to properly secure Safeguards Information (86-24-01)

Pi Q

Approved by:

R.

8609190166 860712 PDR ADDCK 05000261 Q PDR

ENCLOSURE CONTAINS SAFEGUARDS INFORMATION UPON SEFARATION THIS PAGE IS DECONTROLLED.

SAFEGUARDS INFORMATION