

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

SESSION NBR:9006210511 DOC.DATE: 90/06/07 NOTARIZED: NO DOCKET #  
 FACIL:50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light C 05000261  
 AUTH.NAME AUTHOR AFFILIATION  
 REYES,L.A. Region 2, Ofc of the Director  
 RECIP.NAME RECIPIENT AFFILIATION  
 EURY,L.W. Carolina Power & Light Co.

SUBJECT: Forwards Insp Rept 50-261/90-11 on 900411-0510 & notice of violation.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3 + 1/3  
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-1 PD	1 1	LO,R	1 1
INTERNAL:	AEOD	1 1	AEOD/DEIIB	1 1
	AEOD/TPAD	1 1	DEDRO	1 1
	NRR MORISSEAU,D	1 1	NRR SHANKMAN,S	1 1
	NRR/DLPQ/LPEB10	1 1	NRR/DOEA DIR 11	1 1
	NRR/DREP/PEPB9D	1 1	NRR/DRIS/DIR	1 1
	NRR/DST/DIR 8E2	1 1	NRR/PMAS/ILRB12	1 1
	NUDOCS-ABSTRACT	1 1	<del>OE DIR</del>	1 1
	OGC/HDS1	1 1	<u>REG FILE</u> 02	1 1
	RGN2 FILE 01	1 1		
EXTERNAL:	LPDR	1 1	NRC PDR	1 1
	NSIC	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 22 ENCL 22

*Official Copy*

JUN 07 1990

Docket No: 50-261  
License No: DPR-23

Carolina Power and Light Company  
ATTN: Mr. Lynn W. Eury  
Executive Vice President  
Power Supply  
P. O. Box 1551  
Raleigh, NC 27602

Gentlemen:

SUBJECT: NOTICE OF VIOLATION  
NRC INSPECTION REPORT NO. 50-261/90-11

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by L. W. Garner on April 11 - May 10. The inspection included a review of activities authorized for your H. B. Robinson facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

The inspection findings indicate that certain activities appeared to violate NRC requirements. The violation, references to pertinent requirements, and elements to be included in your response are described in the enclosed Notice of Violation.

The violation described in the enclosed Notice is similar to a violation contained in the Notice sent to you by our letter dated June 23, 1988. Recurring violations are of particular concern because the NRC expects licensees to learn from their past failures and to take effective corrective actions. Although NRC does not normally consider monetary civil penalties for Severity Level IV violations, the Enforcement Policy states that such penalties may be imposed for Severity Level IV violations that are similar to previous violations for which the licensee did not effective corrective action. In this case, we have decided not to hold an enforcement conference nor to propose a civil penalty because of the safety significance associated with not performing monthly surveillance testing of the identified instrument logic channels, actions taken to assure the monthly testing of the power range high flux - low setpoint and two-out-of-three loop low flow reactor trip logic channels and your proposed actions associated with testing the intermediate and source range reactor trip logic channels.

7006210511 900607  
FDR ADDER 05000261  
PDC

*Official Copy*  
I-61 III

JUN 07 1983

In your response to the enclosed Notice, you should document the specific actions taken and any additional actions you plan to prevent recurrence of inadequate surveillance testing of Technical Specification required instrumentation. We will review your response, including your proposed corrective actions, and the results of future inspections to determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

In accordance with Section 2.790(a), a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

The responses directed by this letter and its enclosures are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, Pub. L. No. 96-511.

Should you have any questions concerning this letter, please contact us.

Sincerely,

Original signed by

Luis A. Reyes, Director  
Division of Reactor Projects

Enclosures:

1. Notice of Violation
2. NRC Inspection Report

cc w/encls:

C. R. Dietz, Manager  
Robinson Nuclear Project Department  
H. B. Robinson Steam Electric Plant  
P. O. Box 790  
Hartsville, SC 29550

R. E. Morgan, Plant General Manager  
H. B. Robinson Steam Electric Plant  
P. O. Box 790  
Hartsville, SC 29550

Heyward G. Shealy, Chief  
Bureau of Radiological Health  
Dept. of Health and Environmental  
Control  
2600 Bull Street  
Columbia, SC 29201

(cc w/encls continued - See page 3)

(cc w/encls cont'd)  
Dayne H. Brown, Director  
Division of Radiation Protection  
N. C. Department of Environment,  
Health & Natural Resources  
P. O. Box 27687  
Raleigh, NC 27611-7687

McCuen Morrell, Chairman  
Darlington County Board of Supervisors  
County Courthouse  
Darlington, SC 29535

Richard E. Jones, General Counsel  
Carolina Power and Light Company  
P. O. Box 1551  
Raleigh, NC 27602

H. A. Cole  
Special Deputy Attorney General  
State of North Carolina  
P. O. Box 629  
Raleigh, NC 27602

Avery Upchurch, Chairman  
Triangle J Council of Governments  
100 Park Drive  
P. O. Box 12276  
Research Triangle Park, NC 27709

Robert Gruber  
Executive Director  
Public Staff - NCUC  
P. O. Box 29520  
Raleigh, NC 27626-0520

bcc w/encls:  
Document Control Desk

NRC Resident Inspector  
U.S. Nuclear Regulatory Commission  
Route 5, Box 413  
Hartsville, SC 29550

RII:DRP  
RCarroll  
06/ /90

RII:DRP  
HDance  
06/ /90

RII:DRP  
DVerrelli  
06/ /90

*out of office*  
RII:DRP  
BHenl  
06/ /90

RII:EICS  
GJenkins  
06/6 /90