offorciar

IE01

NOV 0 3 1991

Docket No. 50-261 License No. DPR-23

Carolina Power and Light Company ATTN: Mr. Lynn W. Eury **Executive Vice President** Power Supply P. O. Box 1551 Raleigh, NC 27602

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-261/91-26

This refers to the inspection conducted by A. T. Boland of this office on November 18-22, 1991. The inspection included a review of activities authorized for your H. B. Robinson facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

In addition, an apparent repeat violation was identified and is being considered for escalated enforcement action in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions" (Enforcement Policy), 10 CFR Part 2, Appendix C (1991). The apparent violation involves the failure to adequately correct previously identified exercise weaknesses and relates to emergency classification assessment. Accordingly, no Notice of Violation is presently being issued for these inspection findings. Please be advised that the characterization of the apparent violation described in the enclosed inspection report may change as a result of further NRC review.

An enforcement conference to discuss this apparent violation has been scheduled for December 20, 1991 at 1:00 p.m. The purpose of this conference is to discuss the apparent violation, its cause and safety significance; to provide you the opportunity to point out any errors in our inspection report; to provide an opportunity for you to present your proposed corrective actions; and to discuss any other information that will help us determine the appropriate enforcement action in accordance with the Enforcement Policy. You will be advised by separate correspondence of the results of our deliberations on this matter. No response regarding this apparent violation is required at this time.

In accordance with 10 CFR 2.790(a), a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

9112120055 911103 PDR ADOCK 05000261

PDR

Carolina Power and Light Company 2

Should you have any questions concerning this letter, please contact us.


Sincerely,

51

J. Philip Stohr, Director Division of Radiation Safety and Safeguards

Enclosure: NRC Inspection Report

cc w/encl: C. R. Dietz, Vice President Robinson Nuclear Project Department H. B. Robinson Steam Electric Plant P. O. Box 790 Hartsville, SC 29550



Heyward G. Shealy, Chief Bureau of Radiological Health Dept. of Health and Environmental Control 2600 Bull Street Columbia, SC 29201

Dayne H. Brown, Director Division of Radiation Protection N. C. Department of Environment, Health & Natural Resources P. O. Box 27687 Raleigh, NC 27611-7687

cc w/encl: (Cont'd on page 3)



Carolina Power and Light Company 3

(cc w/encl: Cont'd)
McCuen Morrell, Chairman
Darlington County Board of Supervisors
County Courthouse
Darlington, SC 29535

Mr. H. Ray Starling Manager - Legal Department P. O. Box 1551 Raleigh, NC 27602

H. A. Cole Special Deputy Attorney General State of North Carolina P. O. Box 629 Raleigh, NC 27602

Robert Gruber Executive Director Public Staff - NCUC P. O. Box 29520 Raleigh, NC 27626-0520

J. D. Kloosterman, Director Regulatory Compliance H. B. Robinson Steam Electric Plant P. O. Box 790 Hartsville, SC 29550 bcc w/encl: Document Control Desk H. Christensen, RII R. Lo, NRR J. Heard, FEMA, RIV R. Erickson, NRR/EPB

.

NRC Resident Inspector U.S. Nuclear Regulatory Commission Route 5, Box 413 Hartsville, SC 29550

