FORD 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9308050091 DOC.DATE: 93/07/02 NOTARIZED: NO DOCKET # FACIL:50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light C 05000261 AUTH.NAME AUTHOR AFFILIATION
MERSCHOFF, E.W. Region 2 (Post 820201)

MERSCHOFF, E.W. Region 2 (Post 820201)
RECIP.NAME RECIPIENT AFFILIATION
DIETZ, C.R. Carolina Power & Light Co.

SUBJECT: Forwards insp rept 50-261/93-11 on 930515-0611 & notice of violation. Concerned about violation involving erroneous deletion of procedural precaution due to similarity to noncited violation rnoted in insp rept 50-261/93-05.

NOTES:

	RECIPIENT ID CODE/NAME PD2-1 PD	COPIE LTTR 1		RECIPIENT ID CODE/NAME MOZAFARI,B	COP: LTTR 1		
INTERNAL:	AEOD/DEIB AEOD/DSP/TPAB DEDRO NRR/DRCH/HHFB NRR/DRSS/PEPB NRR/PMAS/ILPB2 OE DIR REG FILE 02 RGN2 FILE 01	1 1 1 1 1 1 1	1 1 1 1 1 1 1	AEOD/DSP/ROAB AEOD/TTC NRR/DORS/OEAB NRR/DRIL/RPEB NRR/PMAS/ILPB1 NUDOCS-ABSTRACT OGC/HDS2 RES/HFB	1 1 1 1 1 1	1 1 1 1 1 1	
EXTERNAL:	EG&G/BRYCE,J.H. NSIC	1	1	NRC PDR	1	1	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK. ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

i their

Docket No.: 50-261 License No.: DPR-23

Carolina Power and Light Company

ATTN: Mr. C. R. Dietz Vice President

H. B. Robinson Steam Electric Plant

Unit 2

P. O. Box 790

Hartsville, SC 29550-0790

Gentlemen:

SUBJECT:

NOTICE OF VIOLATION

(NRC INSPECTION REPORT NO. 50-261/93-11)

This refers to the inspection conducted by W. T. Orders of this office on May 15 - June 11, 1993. The inspection included a review of activities authorized for your H. B. Robinson facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements as specified in the enclosed Notice of Violation (Notice). We are particularly concerned about the violation involving an erroneous deletion of a procedural precaution, for it is similar to a non-cited violation contained in Inspection Report 93-05 which was sent to you by our letter dated April 9, 1993. Recurring violations are of particular concern because the NRC expects licensees to learn from their past failures and to take effective corrective actions. Although the NRC does not normally consider monetary civil penalties for Severity Level IV violations, the Enforcement Policy states that such penalties may be imposed for severity level IV violations for which the licensee did not take effective corrective action. In this case, we have decided not to hold an enforcement conference nor to propose a civil penalty because of the minor significance of the violation and the prompt corrective actions initiated upon the identification of this violation.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional

9308050091 930702 PDR ADDCK 05000261 2

actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

The responses directed by this letter and its enclosed Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, Pub. L. No. 96-511.

Should you have any questions concerning this letter, please contact us.

Sincerely,

Original signed by: Ellis W. Merschoff

Ellis W. Merschoff, Director Division of Reactor Projects

Enclosures:

- 1. Notice of Violation
- 2. NRC Inspection Report

cc w/encls: Mr. W. T. Flanagan Acting Plant General Manager H. B. Robinson Steam Electric Plant P. O. Box 790 Hartsville, SC 29550

Mr. W. S. Orser Executive Vice President Nuclear Generation Carolina Power & Light Company P. O. Box 1551 Mail Code - CPB 12 Raleigh, NC 27602

Mr. H. W. Habermeyer, Jr. Vice President Nuclear Services Department Carolina Power & Light Company P. O. Box 1551 - Mail OHS7 Raleigh, NC 27602

(cc w/encls cont'd - See page 3)

(cc w/encls cont'd)
Heyward G. Shealy, Chief
Bureau of Radiological Health
Dept. of Health and Environmental
 Control
2600 Bull Street
Columbia, SC 29201

Dayne H. Brown, Director
Division of Radiation Protection
N. C. Department of Environment,
Health & Natural Resources
P. O. Box 27687
Raleigh, NC 27611-7687

McCuen Morrell, Chairman
Darlington County Board of Supervisor
County Courthouse
Darlington, SC 29535

H. Ray Starling Vice President - Legal Department Carolina Power and Light Co. P. O. Box 1551 Raleigh, NC 27602

H. A. Cole Special Deputy Attorney General State of North Carolina P. O. Box 629 Raleigh, NC 27602

Robert Gruber Executive Director Public Staff - NCUC P. O. Box 29520 Raleigh, NC 27626-0520

J. L. Harrison, Manager Regulatory Compliance H. B. Robinson Steam Electric Plant P. O. Box 790 Hartsville, SC 29550

Ms. Gayle B. Nichols Staff Counsel SC Public Service Commission P. O. Box 11649 Columbia, SC 29211 bcc w/encls: H. Christensen, RII S. Vias, RII B. Mozafari, NRR Document Control Desk

NRC Resident Inspector
U. S. Nuclear Regulatory Commission
Route 5, Box 413
Hartsville, SC 29550

RII:DRP RCarroll:tj 06/36/93 RII:DRP HChristensen 07/1/93 RII:DRP

DVerrelli

07/1/93

RIJ:FCV9 GJenkins 07/2 /93