October 2, 1995

Carolina Power & Light Company
ATTN: Mr. C. S. Hinnant
Vice President
H. B. Robinson Steam Electric Plant
Unit 2
3581 West Entrance Road
Hartsville, SC 29550

SUBJECT: PLANT PERFORMANCE REVIEW (PPR) - ROBINSON

Dear Mr. Hinnant:

On September 18, 1995, the NRC staff completed the semiannual Plant Performance Review (PPR) of the Robinson Steam Electric Plant. The staff conducts these reviews for all operating nuclear power plants to develop an integrated understanding of safety performance. The results are used by regional management to facilitate planning and allocation of inspection resources. The PPR for Robinson involved the participation of all Regional Technical Divisions and NRR in evaluating inspection results and safety performance information for the period from March 1995 to September 1995. PPRs provide regional management with a current summary of licensee performance and serve as inputs to the NRC Systematic Assessment of Licensee Performance (SALP) and senior management meeting (SMM) reviews.

This letter advises you of our planned inspection effort resulting from the Robinson PPR review. It is provided to minimize the resource impact on your staff and to allow for scheduling conflicts and personnel availability issues to be resolved in advance of inspector arrival onsite. The enclosure details our inspection plan for the next six months. The rationale or basis for each inspection outside the core inspection program is provided so that you are aware of the reason for emphasis in these program areas. Resident inspections are not listed due to their ongoing and continuous nature.

We will inform you of any changes to the inspection plan. If you have any questions, please contact D. Verrelli at (404) 331-5535.

Sincerely

Ellis W. Merschoff, Director Division of Reactor Projects

9510180112 951002 PDR ADOCK 05000261 G PDR

Docket No.: 50-261 License No.: DPR-23

Enclosure: Inspection Plan

cc w/encl: (See page 2)

176107

MAY

TEO

cc w/encl:
Dale E. Young
Plant Manager
H. B. Robinson Steam Electric Plant
3581 West Entrance Road
Hartsville, SC 29550

J. Cowan, Manager Nuclear Services & Environmental Support Department, MS OHS7 Carolina Power & Light Company P. O. Box 1551 Raleigh, NC 27602

R. M. Krich, Manager Regulatory Affairs H. B. Robinson Steam Electric Plant 3581 West Entrance Road Hartsville, SC 29550

Max Batavia, Chief Bureau of Radiological Health Dept. of Health and Environmental Control 2600 Bull Street Columbia, SC 29201

Dayne H. Brown, Director
Division of Radiation Protection
N. C. Department of Environmental
Commerce & Natural Resources
P. O. Box 27687
Raleigh, NC 27611-7687

R. E. Jones General Counsel - Legal Department Carolina Power & Light Co. P. O. Box 1551 Raleigh, NC 27602

Karen E. Long Assistant Attorney General State of North Carolina P. O. Box 629 Raleigh, NC 27602

(cc w/encl cont'd - See page 3)

(cc w/encl cont'd)
Robert P. Gruber
Executive Director
Public Staff - NCUC
P. O. Box 29520
Raleigh, NC 27626-0520

Public Service Commission State of South Carolina P. O. Box 11649 Columbia, SC 29211

Hartsville Memorial Library 147 W. College Avenue Hartsville, SC 29550

<u>Distribution w/encl</u>:

D. Verrelli, RII B. Mozafari, NRR G. A. Hallstrom, RII PUBLIC

NRC Resident Inspector U. S. Nuclear Regulatory Commission 2112 Old Camden Road Hartsville, SC 29550

SEND TO PUBLIC DOCUMENT ROOM?			YES NO			
OFFICE	RII:DR	RII:DRP	RII:DRSS	RII:DRS		
SIGNATURE	A	7	00	11		
NAME	JStareforti	DVerrelli	KBarr	CCalette		
DATE	09 /15/35	95796,95	pg / 0 / 95	09 / 0/ 95	09 / / 95	09 / / 95
COPY?	YES) NO	YES NO	YES NO	(XES) NO	YES NO	YES NO

OFFICIAL REGORD COPY DOCUMENT NAME: P:\ROBINSON.PPR

ROBINSON INSPECTION PLAN					
Inspection Title	Dates	# Insp			
Emergency Preparedness Exercise Core Inspection Module 82301/82302	10/30-11/3/95	3			
Initial Examinations	2/12-16/96	3			
Maintenance Observations Core (Resident Core to be done bi-monthly by DRS Inspectors) Modules 62703/92902	10/1/95- 3/31/96	1			
Surveillance Observations Core (Resident Core to be done bi-monthly by DRS (nepectors) Modules 61726/92902	10/1/95- 3/31/96	1			
Maintenance Procedure Regional Init Insp ¹ Module 62703	To be decided	1			
Engineering Regional Initiative ² Inspection Module 37550	2/5-9&12- 16/96	3			
Safeguards Core Inspection Module 81700	2/26-3/1/96	1			
Radiological Effluents and Chemistry Core Inspection Module 84750/86750	12/4-8/95	1			

¹ Procedural controls identified by SALP Board as a challenge.

 $^{^{2}}$ Identification of discrepant conditions identified by SALP Board as a challenge.