# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

FACIL:50 AUTH.NA GROOMS,3	D-261 H.B. Robins AME AUTHOR J. Carolin	on Plant AFFILIA a Power	, Uni TION & Ligi	9 <del>1/08/31.</del> NOTARIZE t 2, Carolina Powe ht Co. ht Co.								
ROBINSÓN,H.B. Carolina Power & Light Co. CHAMBERS,R.H. Carolina Power & Light Co. RECIP.NAME RECIPIENT AFFILIATION												
							Ι					
SUBJECT: Monthly operating rept for Aug 1991 for HB Robinson Steam Electric Plant Unit 2.W/910910 ltr.												
DISTRIBUTION CODE: IE24D COPIES RECEIVED:LTR $\frac{1}{2}$ ENCL $\frac{1}{2}$ SIZE: <u>6</u> TITLE: Monthly Operating Report (per Tech Specs)												
NOTES:		1.05010	(101				/					
NOIES:				· · ·			Α					
	RECIPIENT ID CODE/NAME	COPIE		RECIPIENT ID CODE/NAME	COPIE LTTR E		_					
	PD2-1 LA			PD2-1 PD		1	D					
	LO,R	1	1				D					
INTERNAL:	AEOD/DOA	1	1	AEOD/DSP/TPAB	1	1	C					
	NRR/DLPQ/LPEB10	1 1 1	1 1 1	NRR/DOEA/OEAB	1	1	S					
	REG FILE 01	T	Ŧ	RGN2	T	T						
EXTERNAL:	EG&G BRYCE,J.H NSIC	1 1	1 1	NRC PDR	1	1						

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED! TOTAL NUMBER OF COPIES REQUIRED: LTTR 14 ENCL 14

R

Ι

D

S

/

Α

D

D

S



#### **Carolina Power & Light Company**

ROBINSON NUCLEAR PROJECT DEPARTMENT POST OFFICE BOX 790 HARTSVILLE, SOUTH CAROLINA 29550

SEP 1 0 1991

Robinson File: 15505

Serial: RNPD/91-2260

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D. C. 20555

> H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2 DOCKET NO. 50-261 LICENSE NO. DPR-23 MONTHLY OPERATIONS REPORT

Gentlemen:

In accordance with Technical Specification 6.9.1.c for the H. B. Robinson Steam Electric Plant, Unit No. 2, Carolina Power and Light Company herewith submits the report of operation statistics and shutdown experience for the month of August, 1991.

Very truly yours,

Roy H.

R. H. Chambers General Manager H. B. Robinson S. E. Plant

SAB:dwm

Enclosure

cc: S. D. Ebneter L. W. Garner

109170242 9108 PDR

	DATA REPORT N UNIT 2		PAGE 1 RPD36-000		
Page 1 of 5 OFERATING STATUS	100	CKET NO. 050-( MPLETED BY JA LEPHONE (803			
OF LIVERTIES OF MILLOU	i tau k		The first first of the second s		
<ol> <li>UNIT NAME: ROBINSON UNIT 2</li> <li>REPORTING PERIOD: AUGUST 91</li> <li>LICENSED THERMAL POWER (MWT): 2300</li> <li>NAMEPLATE RATING (GROSS MWE): 739.0</li> <li>DESIGN ELECTRICAL RATING (NET MWE):</li> <li>MAX DEPENDABLE CAPACITY (GROSS MWE)</li> <li>MAX DEPENDABLE CAPACITY (NET MWE):</li> </ol>	on si   Pit.   Shipp 700.0   React : 700.0   Dry F	700.0   Dry Fuel Storage Module.			
8. IF CHANGES OCCUR IN CAPACITY RATING GIVE REASONS: Item #7 (MDC) increased re-evaluation of operati	5 (ITEMS 3 THF to 683 MWE from				
9. POWER LEVEL TO WHICH RESTRICTED IF 10. REASONS FOR RESTRICTION IF ANY: "B" fail	ANY (NET MWE): Condensate Pump ed shaft.	Approximately out of service	70% (as of 8/30/91) due to a		
	THIS MONTH	YR TO DATE	CUMUL ATIVE		
<pre>11. HOURS IN REPORTING PERIOD 12. NUMBER OF HOURS REACTOR CRITICAL 13. REACTOR RESERVE SHUTDOWN HRS 14. HOURS GENERATOR ON LINE 15. UNIT RESERVE SHUTDOWN HOURS 16. GROSS THERMAL ENERGY GEN. (MWH) 17. GROSS ELEC. ENERGY GENERATED (MWH) 18. NET ELEC. ENERGY GENERATED (MWH) 19. UNIT SERVICE FACTOR 20. UNIT AVAILABILITY FACTOR 21. UNIT CAP. FACTOR (USING MDC NET) 22. UNIT CAP. FACTOR (USING DER NET) 23. UNIT FORCED OUTAGE RATE 24. SHUTDOWNS SCHED. OVER NEXT 6 MONTHS</pre>	744.00 681.59 .00 676.55 .00 1514069.76 487316.00 462253.00 90.93 90.93 90.93 90.97 88.76 9.07 (TYPE, DATE,	5831.00 4202.01 .00 4142.50 .00 9179036.88 3004306.00 2851402.00 71.04 71.04 71.04 71.60 69.86 1.60 AND DURATION	179735.00 125460.26 3314.65 122615.07 23.20 247712506.08 80224241.00 75748880.00 68.22 68.23 63.32 60.21 15.21 OF EACH): None		

25. IF SHUTDOWN AT END OF REPORT PERIOD, ESTIMATED DATE OF START UP:  $_{\rm N/A}$  26. UNITS IN TEST STATUS (PRIOR TO COMMERCIAL OPERATION): FORECAST ACHIEVED

INITIAL CRITICALITY	  
INITIAL ELECTRICITY	 
COMMERCIAL OPERATION	 

		T PERFORMANCE B — AVERAGE D ROBINSON UNI	AILY POWER EVEL RPD3	1 9-000
	sure to Serial: RNPD/91-2260 2 of 5		DOCKET NO. 050-0261 COMPLETED BY JACKIE GROOMS TELEPHONE (803)383-4524	
AUGUS	ST 1991			
DAY	AVG. DAILY POWER LEVEL (MWE-NET)	DAY AVG	. DAILY POWER LEVEL (MWE-NET)	
1	706	17	-25	
2	709	18	101	
3	709	1 ዎ	671	
4	709	20	708	
5	707	21	704	
6	708	22	703	
7	709	23	704	
8	710	24	704	
9	712	25	705	
10	709	. 26	706	
· 11	655	27	706	
12	704	28	705	
13	704	29	705	
14	705	30	188	

1.16 - 8

•

for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG- 0161) 5 Exhibit 1 - Same Source	1-Manual 2-Manual Scram. 3-Automatic Scram. 4-Other (Explain)	I-Man 2-Man 3-Auto 4-Otho	nination	-plain) cense Exar slain)	r Test r Test striction ing & Li ror (Exp	A-cquipment Failure (Explain) B-Maintenance of Test C-Refueling D-Regulatory Restriction E-Operator Training & License Examination F-Administrative F-Administrative G-Operational Error (Explain) H-Other (Explain)	A-Eq B-Mai D-Reg E-Ope F-Ada H-Oth	9/77)
4 4 Exhibit G - Instructions for Preparation of Data	ual	F	υ	.plain)	ilure (Ex	n: lipment Fai	2 Reason: A-Equip	 Forced Scheduled
			·					
Ramp back up to full power OST-551 and repair of "B" : oil sightglass.	Valvex Pump XX	N/A HH		. р			N	081191
Ramp down in power to perform OST-551 and replace "B" feed oil sightglass.	Valvėx Pump XX	N/A HH		Ц	в		ц	081091
Cause & Corrective Action to Prevent Recurrence	Component Code <sup>5</sup>	System Code <sup>4</sup>	Licensec Event Report #	Method of Shutting Down Reactor <sup>3</sup>	Reason <sup>2</sup>	Duration (Hours)	Type <sup>I</sup>	Date
IS DOCKET NO. UNIT NAME COMPLETED BY TELEPHONE	REDUCTION	POWER R	UNIT SHUTDOWNS AND POWER REDUCTIONS REPORT MONTH August	UNIT	•			

Enclosure to Serial: RNPD/91-2260 Page 3 of 5

• ŕ,

x •.

Enclosure to Serial: RNPD/91-2260 Page 4 of 5

# UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO.	050-0261
UNIT NAME	H. B. Robinson
DATE	09/06/91
COMPLETED BY	J. W. Grooms
TELEPHONE	(803) 383-4524

REPORT MONTH \_\_\_\_\_August

Νø.	Date	Typel	Duration (Hours)	Reason <sup>2</sup>	Method of Shutting Down Reactor <sup>3</sup>	Licensec Event Report #	System Code <sup>4</sup>	Component Code <sup>5</sup>	Cause & Corrective Action to Prevent Recurrence
0803	081691	F	2.58	Η	2	91-009	SH	XXXXXX	Ramped off line due to Tech. Spec. Table 3.5-2, Item 5. At 1200 hrs. on 8/16/91, Tech. Spec. 3.0 was entered which required the unit to be in hot shutdown in 8 hrs. and in cold shutdown in an additional 30 hrs. The cause was an inability to meet minimum degree of redundancy on OT Delta-T reactor protection channels. All three channels were out of service due to electromechanical delays being set too high. The problem was corrected before having to take the unit to cold shutdown. NOTE: While subcritical, a reactor trip was generated. See LER-91-010.
0804	081691	F	44.52	H			SH	XXXXXX	Unit maintained in hot shutdown per Tech. Spec. Table 3.5-2, Item 5.
1 F: For S: Sch		B-Ma C-Ref D-Reg E-Ope F-Ad G-Op	on: uipment Fai intenance of Sueling gulatory Re erator Train ministrative erational Er ter (Explain	f Test striction ing & Li ror (Exp	cense Exai	3 nination	3-Auto		4 Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG- 0161) 5 Exhibit I - Same Source

Enclosure to Serial: RNPD/91-2260 Page 5 of 5

## UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH August

 DOCKET NO.
 050-0261

 UNIT NAME
 H. B. Robinson

 DATE
 09/06/91

 COMPLETED BY
 J. W. Grooms

 TELEPHONE
 (803) 383-4524

ί.

Νø,	Date	Type <sup>l</sup>	Duration (Hours)	Reason <sup>2</sup>	Method of Shutting Down Reactor-3	Licensee Event Report #	System Cude <sup>4</sup>	Component Code <sup>5</sup>	Cause & Corrective Action to Prevent Recurrence
0804 (Cont	081691 Inued)	F	44.52	Н			SH	XXXXXX	Corrective Action: Repair inoperable OT Delta-T Rx protection channels.
0805	081891	S	6.41	Η	2		SH	XXXXXX	Ramp up to 100% power. Comments: OT Delta-T channels put back in service after repairs. Reactor critical at 1152 and put online at 1432.
0806	083091	F	22.93	A	1	91-011	нн	Pump XX	Reactor trip due to steam/feedwater flow mismatch with low low level in "C" Steam Generator.
									Corrective Action: Bring unit critical. Ramp up and maintain a reduced power level until repair of "B" Condensate Pump is complete.
l F: For S: Sch (9/77)		B-Ma C-Ref D-Ref E-Op F-Ad G-Op	on: uipment Fai intenance of fueling gulatory Res erator Train ministrative erational Er ner (Explain	Test striction ing & Li ror (Exp	cense Exai	3 nination	Methoo 1-Manu 2-Manu 3-Auto		4 Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG- 0161) 5 Exhibit I - Same Source