interest. Again adjustments are made to account for pressure and temperature instrumentation error.

The overpressure protection system consists of two operable pressurizer Power Operated Relief Valves (PORVs) connected to the nitrogen supply system, backup nitrogen accumlators, the station instrument air system, and the associated electronics.

<u>References</u>

- S. E. Yanichko, "Carolina Power & Light Company, H. B. Robinson Unit No. 2 Reactor Vessel Radiation Surveillance Program," Westinghouse Nuclear Energy Systems - WCAP-7373 (January 1970).
- E. B. Norris, "Reactor Vessel Material Surveillance Program for H. B. Robinson Unit No. 2, Analysis of Capsule V," Southwest Research Institute - Final Report SWRI Project No. 02-4397.