

March 20, 1990

Docket No. 50-261

Mr. Lynn W. Eury
Executive Vice President
Power Supply
Carolina Power & Light Company
Post Office Box 1551
Raleigh, North Carolina 27602

Dear Mr. Eury:

SUBJECT: UNIMPLEMENTED UNRESOLVED SAFETY ISSUES AT H.B. ROBINSON
STEAM ELECTRIC PLANT, UNIT NO. 2

On October 19, 1989, the staff issued Generic Letter (GL) 89-21 which requested information concerning the status of implementation of unresolved safety issues (USI) at your facility. Based on your response to this GL, dated November 27, 1989, our review of Agency records and discussions between your staff and the NRC Project Manager, the NRC staff has compiled the enclosed list representing our assessment of USI implementation. These results were presented to the Commission at a meeting on February 14, 1990.

Enclosure 1 to this letter presents the staff's understanding of the current status of all unimplemented USI for the H. B. Robinson Steam Electric Plant, Unit No. 2. The staff encourages your effort to complete the unimplemented USI.

If you have questions or comments about the enclosed information please contact your NRC Project Manager.

Sincerely,

Brenda Mozafari/for

Ronnie H. Lo, Senior Project Manager
Project Directorate II-1
Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation

9003260142 900320
PDR ADICK 05000261
PDC

Enclosure:
As stated
cc w/enclosure:
See next page

DISTRIBUTION

Docket File		NRC PDR	
Local PDR		S. Varga	14-E-4
G. Lainas	14-H-3	E. Adensam	14-B-20
P. Anderson	14-B-20	R. Lo	14-B-20
OGC	15-B-18	E. Jordan	MNBB-3302
ACRS (10)	P-315	Robinson	
K. Eccleston			

OFC	: LA: PD/IV-1	: PM: PDII-1	: D: PDII-1	:	:	:
NAME	: PAnderson	: RLo: sw	: EAdensam	:	:	:
DATE	: 3/15/90	: 3/20/90	: 3/20/90	:	:	:

DF01 III m/A-1



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

March 20, 1990

Docket No. 50-261

Mr. Lynn W. Eury
Executive Vice President
Power Supply
Carolina Power & Light Company
Post Office Box 1551
Raleigh, North Carolina 27602

Dear Mr. Eury:

SUBJECT: UNIMPLEMENTED UNRESOLVED SAFETY ISSUES AT H.B. ROBINSON
STEAM ELECTRIC PLANT, UNIT NO. 2

On October 19, 1989, the staff issued Generic Letter (GL) 89-21 which requested information concerning the status of implementation of unresolved safety issues (USI) at your facility. Based on your response to this GL, dated November 27, 1989, our review of Agency records and discussions between your staff and the NRC Project Manager, the NRC staff has compiled the enclosed list representing our assessment of USI implementation. These results were presented to the Commission at a meeting on February 14, 1990.

Enclosure 1 to this letter presents the staff's understanding of the current status of all unimplemented USI for the H. B. Robinson Steam Electric Plant, Unit No. 2. The staff encourages your effort to complete the unimplemented USI.

If you have questions or comments about the enclosed information please contact your NRC Project Manager.

Sincerely,

Brenda Mozafari for

Ronnie H. Lo, Senior Project Manager
Project Directorate II-1
Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation

Enclosure:
As stated

cc w/enclosure:
See next page

Mr. L. W. Eury
Carolina Power & Light Company

H. B. Robinson Steam Electric
Plant, Unit No. 2

cc:

Mr. R. E. Jones, General Counsel
Carolina Power & Light Company
P. O. Box 1551
Raleigh, North Carolina 27602

Mr. Dayne H. Brown, Director
Department of Environmental,
Health and Natural Resources
Division of Radiation Protection
P. O. Box 27687
Raleigh, North Carolina 27611-7687

Mr. H. A. Cole
Special Deputy Attorney General
State of North Carolina
P. O. Box 629
Raleigh, North Carolina 27602

Mr. Robert P. Gruber
Executive Director
Public Staff - NCUC
P. O. Box 29520
Raleigh, North Carolina 27626-0520

U.S. Nuclear Regulatory Commission
Resident Inspector's Office
H. B. Robinson Steam Electric Plant
Route 5, Box 413
Hartsville, South Carolina 29550

Mr. C. R. Dietz
Manager, Robinson Nuclear Project
Department
H. B. Robinson Steam Electric Plant
P. O. Box 790
Hartsville, South Carolina 29550

Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta Street
Suite 2900
Atlanta, Georgia 30323

Mr. Heyward G. Shealy, Chief
Bureau of Radiological Health
South Carolina Department of Health
and Environmental Control
2600 Bull Street
Columbia, South Carolina 29201

Mr. R. Morgan
General Manager
H. B. Robinson Steam Electric Plant
P. O. Box 790
Hartsville, South Carolina 29550

ENCLOSURE

List of Incomplete USIs

<u>USI</u>	<u>TITLE</u>	<u>Estimated Implemented Date</u>	<u>Remarks</u>
A-44	Station Blackout	9/30/92	
A-46	Seismic Qualification of Equipment in Operating Plants	No estimate	Pending approval of generic document
A-47	Safety Implication of Control Systems	No estimate	Pending response to GL 89-14