REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8709030439 DOC. DATE: 87/08/28 NOTARIZED: NO DOCKET # FACIL: 50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light C 05000261 AUTH. NAME AUTHOR AFFILIATION

GRACE, J. N. Region 2, Office of Director

RECIP. NAME RECIPIENT AFFILIATION
UTLEY, E. E. Carolina Power & Light Co.

SUBJECT: Forwards 870821 meeting summary of Insp Rept 50/261-26 re unlocked protected area door allowing entry of unsearched,

unbadged licensee employee & unbadged unsearched & unthorized individual into area. (Ref 10CFR2.790 & 73.21).

NOTES:

	RECIPIENT ID CODE/NAME PD2-1 LA ECGLESTON, K	COPIES LTTR ENCL 1 0 1	RECIPIENT ID CODE/NAME PD2-1 PD	COPIES LTTR ENCL 1
INTERNAL:	AEOD/DOA NRB/DALE/SIB REG FILE 02	1 1 1	NRR/DRIS/SGB NRR/PMAS/ILRB RGN2 FILE 01	1 1 1
EXTERNAL:	LPDR NSIC	1 1	NRC PDR	1

SAFEGUARDS INFORMATION

AUG 2 8 1987

Docket No. 50-261 License No. DPR-23

Carolina Power and Light Company
ATTN: Mr. E. E. Utley
Senior Executive Vice President
Power Supply and Engineering
and Construction
P. O. Box 1551
Raleigh, NC 27602

Gentlemen:

SUBJECT: MEETING SUMMARY - NRC INSPECTION REPORT NO. 50-261/87-26

This letter refers to the Enforcement Conference held at our request at the Region II Office on August 21, 1987, to discuss the findings of the inspection conducted by Ms. O. Masnyk at your H. B. Robinson facility on August 13-14, 1987. The inspection findings related to an unlocked protected area door allowing the entry of an unsearched, unbadged licensee employee, and an unbadged, unsearched, unauthorized individual into the protected area. A meeting summary is enclosed.

Our concerns about this incident were expressed to Carolina Power and Light Company representatives at the meeting. The issues discussed at the meeting and addressed in Inspection Report No. 50-261/87-26 dated August 11, 1987, and the enclosure to this letter are under consideration for escalated enforcement action. Accordingly, no Notice of Violation is being issued at this time and no response is required. However, please be advised that the number and characterization of the violations may change as a result of further NRC review.

It is our opinion that this meeting was beneficial and has provided for a better understanding of inspection findings and enforcement issues.

In accordance with 10 CFR 2.790(d) and 10 CFR 73.21, safeguards activities and security measures are exempt from public disclosure; therefore, the enclosure to this letter will \underline{not} be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

J. Nelson Grace Regional Administrator

Enclosure: (See page 2)

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED.

SAFEGUARDS INFORMATION

IE-0/1/0

8709030439 870828 PDR ADDCK 05000261

SAFEGUARDS INFORMATION AUG 2 8 1987.

Carolina Power and Light Company

Enclosure:
Meeting Summary
(Safeguards Information)

cc w/encl:

G. P. Beatty, Jr., Vice President Robinson Nuclear Project Department R. E. Morgan, Plant General Manager

bcc w/encl: NRR/DRIS/SB

bcc w/o encl: NRC Resident Inspector Document Control Desk, 016 State of North Carolina

RII RII RII RII ONW OMasnyk DMcGuire WcTine 05t 08/27/87 08/27/87 08/27/87 08/27/87 08/27/87

03tobn P 08/2 /87 0

PFredrickson 08/. x/87 DVerrelli 08/3/87

RTI

LReyes 08/∴√87 RII

GJenkins

08/28/87

RII /

RII

RGoodard MErnst 08/ /87 08/18/87 ENCLOSURE CONTAINS
SAFEGUA INFORMATION
PON SEPARATION THIS
IS DECONTROLLED.

SAFEGUARDS INFORMATION