

JUL 27 1988

yellow

Docket No. 50-261
License No. DPR-23

Carolina Power and Light Company
ATTN: Mr. E. E. Utley
Senior Executive Vice President
Power Supply and Engineering
and Construction
P. O. Box 1551
Raleigh, NC 27602

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-261/88-17

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by J. L. Coley and G. A. Hallstrom on June 27 - July 1, 1988. The inspection included a review of activities authorized for your Robinson facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

RS

Alan R. Herdt, Chief
Engineering Branch
Division of Reactor Safety

Enclosure:
NRC Inspection Report

cc w/encl:
G. P. Beatty, Jr., Vice President
Robinson Nuclear Project Department
R. E. Morgan, Plant General Manager

bcc w/encl: (See page 2)

8808100245 880727
PDR ADDCK 05000261
PDC

11
TFO1

JUL 27 1988

Carolina Power and Light Company

2

bcc w/encl:
NRC Resident Inspector
DRS, Technical Assistant
Document Control Desk
State of South Carolina

RII

JLC
JLColey:ser
07/8/88

RII

GAHallstrom
07/8/88

RII

DBlake
07/21/88

RII

PFredrickson
07/10/88